

Risk

District I _____ P.O. Box 1980, Hobbs, NM District II _____ P.O. Drawer, Artesia, NM 88211 District III _____ 1000 Rio Brazos Rd. Aztec, NM 87410	State Of New Mexico Energy, Minerals and Natural Resources Department OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088	SUBMIT 1 COPY TO APPROPRIATE DISTRICT OFFICE AND 1 COPY TO SANTA FE OFFICE (Revised 3/9/94)
--	--	--

RECEIVED
 JUL - 9 1999
 OIL CON. DIV.
 DIST. 3

PIT REMEDIATION AND CLOSURE REPORT

Operator: <u>Conoco Inc.</u>		Telephone: <u>505-324-5813</u>	
Address: <u>3315 Bloomfield Hwy - Farmington, NM 87401</u>			
Facility Or: <u>Bruington LS 5</u>			
Well Name _____			
Location:	Unit or Qtr/Qtr Sec	<u> </u> C <u> </u> Sec	<u>5</u> T <u>30</u> N R <u>11</u> W County <u>San Juan</u>
Pit Type:	Separator <u> </u> X <u> </u>	Dehydrator <u> </u>	Other <u> </u>
Land Type:	BLM <u> </u> State <u> </u> Fee <u> </u>	<u> </u> X <u> </u>	Other <u> </u>
Pit Location: (Attach diagram)	Pit dimension:	length <u>12'</u>	width <u>12'</u> depth <u>3'</u>
	Reference:	wellhead <u> </u> X <u> </u>	other <u> </u>
	Footage from reference:	<u>16'</u>	
	Direction from reference:	<u>358</u> Degrees	East of <u> </u> North West of <u> </u> South

Depth To Ground Water: (Vertical distance from contaminants to seasonal high water elevation of ground water)	Less than 50 feet	(20 points)	
	50 feet to 9 feet	(10 points)	
	Greater than 100 feet	(0 points)	
	Total		<u>0</u>

Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)	Yes (20 points)		
	No (0 points)		
	Total		<u>0</u>

Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)	Less than 200 feet	(20 points)	
	200 feet to 1000 feet	(10 points)	
	Greater than 1000 feet	(0 points)	
	Total		<u>0</u>

RANKING SCORE (TOTAL POINTS): 0


Date Remediation Started: _____		Date Completed: _____	
Remediation Method: (Check all appropriate sections)	Excavation: _____	Approx. cubic yards _____	
	Landfarm _____	Insitu Bioremediation _____	
	Other _____		
Remediation Location: (ie. landfarmed onsite, name and location of offsite facility)	Onsite _____	Offsite _____	
General Description Of Remedial Action:		<u>Sample taken -- till bottom of pit 1' -- back fill with clean soil</u>	
Ground Water Encountered:	No ☒ Yes ☐	Depth _____	
Final Pit:	Sample location	<u>Center of pit -- 3' in off of bottom of pit</u>	
Closure Sampling:	Sample depth	_____ 3'	
(if multiple samples attach sample results and diagram of sample locations and depths)	Sample date	<u>3/10/99</u>	Sample time <u>13:05</u>
Sample Results			
	Benzene (ppm)	_____ 7.3	
	Total BTEX (ppm)	_____ 356.3	
	Field headspace (ppm)	_____ 478	
	TPH	_____ 5700	
Ground Water Sample:	Yes ☐ No ☒	(If yes, attach sample results)	
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF			
DATE	<u>6-28-99</u>	PRINTED NAME	_____
SIGNATURE	<u>[Signature]</u>	AND TITLE	<u>P.L.</u>

Lease Name: Brington LS

Operator: Steve Miller

Date: 3-10-99

Site Security
(Indicate North)



Lease Name: Brington LS

Federal/ Indian Lease No: FEE

CA No.: NM 025825

Unit: C

Legal Description: S: 5 TP: 30 N R: 11 W

County: San Juan, NM

Load line valves :
Sealed during Production

Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM

22-141 50 SHEETS
22-142 100 SHEETS
22-144 200 SHEETS

3-10-99


Bruington LS 5

SEP 12'x12'x3'

358° North 16' From WH. to
CENTER of Pit.

Center of Pit.

Time. 1305
PPM. 478



⊗ Sample Taken
Bottom of Pit 3' IN


Bruington LS 5

BDP 12'x12'x3'


180° South, 64' From WH
to center of Pit.


Center of Pit.

Time. 1300
PPM. 8



⊗ Sample Taken
3' IN From Bottom of Pit





10026

Date: 3-10-99

Page: 1 of 1

Distribution: White - On Site Yellow - LAB Pink - Sampler Goldenrod - Client

OFF: (505) 325-5667



LAB: (505) 325-1556

ANALYTICAL REPORT

Date: 23-Mar-99

Client:	Conoco, Inc.	Client Sample Info:	Bruington LS 5 SEP
Work Order:	9903038	Client Sample ID:	Center of Pit
Lab ID:	9903038-02A	Matrix:	SOIL
Project:	Bruington LS 5	Collection Date:	3/10/99 1:05:00 PM
		COC Record:	10026

Parameter	Result	PQL	Qual	Units	DF	Date Analyzed
DIESEL RANGE ORGANICS		SW8015				Analyst: DC
T/R Hydrocarbons: C10-C28	1400	25		mg/Kg	1	3/17/99
GASOLINE RANGE ORGANICS		SW8015				Analyst: HR
T/R Hydrocarbons: C6-C10	4300	180		mg/Kg	1000	3/19/99
AROMATIC VOLATILES BY GC/PID		SW8021B				Analyst: HR
Benzene	7300	2500		µg/Kg	2500	3/16/99
Toluene	69000	5000		µg/Kg	2500	3/16/99
Ethylbenzene	28000	2500		µg/Kg	2500	3/16/99
m,p-Xylene	200000	5000		µg/Kg	2500	3/16/99
o-Xylene	52000	2500		µg/Kg	2500	3/16/99

Qualifiers:	PQL - Practical Quantitation Limit	S - Spike Recovery outside accepted recovery limits
	ND - Not Detected at Practical Quantitation Limit	R - RPD outside accepted recovery limits
	J - Analyte detected below Practical Quantitation Limit	E - Value above quantitation range
	B - Analyte detected in the associated Method Blank	Surr - Surrogate

P.O. BOX 2606 • FARMINGTON, NM 87499

1 of 1

TECHNOLOGY FOR A HEALTHIER INDUSTRY WITH THE ENVIRONMENT