

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

API # (assigned by OCD) 30-045-21333
Lease Number 5.
State Oil & Gas Lease # 6
Lease Name/Unit Name 7
Atlantic D Com O 8
Well No. 16
Pool Name or Wildcat 9
Blanco Pictured Cliffs
10. Elevation:

OIL & GAS COMPANY

BURLINGTON
RESOURCES

2. Name of Operator

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1450' FSL 1150' FWL, Sec. 2, T-30-N, R-10-W, NMPM, San Juan County

10. Elevation:

Type of Submission
Type of Action
X Notice of Intent
Abandonment
Recompletion
Plugging Back
Casing Repair
Altering Casing
Other - restimulate
Change of Plans
New Construction
Non-Routine Fracturing
Water Shut off
Conversion to Injection

13. Describe Proposed or Completed Operations
It is intended to restimulate the pictured cliffs formation of the subject well in the following manner:

Clean out to plug back total depth at 3235'. Acidize and foam fracture treat the pictured cliffs zone. Clean out and return well to production.

SIGNATURE

(MDW) Regulatory Administrator November 30, 1998

TLM

(This space for State Use)

APPROVED BY
DEPUTY OIL & GAS INSPECTOR, DIST. #3
DEC 4 1998
Date