## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ces and Reports on Wells		
1. Type of Well GAS	DEPENDED July 2 5 1687 1.	5.	SF-078316D
2. Name of Operator	<del></del>	7.	Unit Agreement Na
BURLINGTON	GAS COMPANY		
3. Address & Phone No. of Operato		8.	Well Name & Number Woodriver #1A
PO Box 4289, Farmington, NM		9.	<b>API Well No</b> . 30-045-21723
4. Location of Well, Footage, Sec 1500'FNL, 1600'FWL, Sec.5, T-3			Field and Pool Blanco Mesaverde County and State San Juan Co, NM
Final Abandonment	Casing Repair Water		
13. Describe Proposed or Comple	-	ersion to	Injection
13. Describe Proposed or Comple 5-1-97 MIRU. ND WH. NU BOR 5-2-97 TIH, tag bottom. TO	_X_ Other - Tubing repair	w/178 jt	.s 2 3/8″ 4.7# <b>J</b> -55
Describe Proposed or Comple 5-1-97 MIRU. ND WH. NU BOR 5-2-97 TIH, tag bottom. TO	_X_ Other - Tubing repair  eted Operations  P. SDON.  DOH w/178 jts 2 3/8" tbg. TIH	w/178 jt	.s 2 3/8" 4.7# J-55
Describe Proposed or Comple 5-1-97 MIRU. ND WH. NU BOR 5-2-97 TIH, tag bottom. TO	_X_ Other - Tubing repair  eted Operations  P. SDON.  DOH w/178 jts 2 3/8" tbg. TIH	w/178 jt	.s 2 3/8" 4.7# J-55
Describe Proposed or Comple 5-1-97 MIRU. ND WH. NU BOR 5-2-97 TIH, tag bottom. TO	_X_ Other - Tubing repair  eted Operations  P. SDON.  DOH w/178 jts 2 3/8" tbg. TIH	w/178 jt	.s 2 3/8" 4.7# <b>J</b> -55
13. Describe Proposed or Completed S-1-97 MIRU. ND WH. NU BOE 5-2-97 TIH, tag bottom. TO EUE tbg, landed	_X_ Other - Tubing repair  eted Operations  P. SDON.  DOH w/178 jts 2 3/8" tbg. TIH  @ 5640'. ND BOP. NU WH. RD. R	w/178 jt Rig relea	s 2 3/8" 4.7# J-55
13. Describe Proposed or Completed S-1-97 MIRU. ND WH. NU BOR 5-2-97 TIH, tag bottom. TO EUE tbg, landed	_X_ Other - Tubing repair  eted Operations  P. SDON.  DOH w/178 jts 2 3/8" tbg. TIH  @ 5640'. ND BOP. NU WH. RD. F	w/178 jt Rig relea	s 2 3/8" 4.7# J-55