Form 3-331 (May 1963)

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

UNITED STATES DEPARTMENT OF THE INTERIOR SUBMIT IN TRIPLICATE* (Other Instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. SF078387

REPAIRING WELL

ALTERING CASING

ABANDON MENT*

GEOLOGICA	L SURVEY
-----------	----------

G	A THE PARTY OF THE VALUE	
SUNDRY NOTION OF THE SUNDRY NO	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS (X) OTHER WELL OTHER 2. NAME OF OPERATOR E1 Paso Natural Gas C	ompany	8. FARM OR LEASE NAME HOWELL D
 ADDRESS OF OPERATOR P. O. Box 990, Farmington, NM 87401 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 		3A 10. FIELD AND POOL, OR WILDCAT Blanco MV
900'S, 1840'E	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	11. SEC., T., E., M., OR BLK. AND SUBVEY OR AREA Sec. 31, T-31-N, R-8-W N.M.P.M. 12. COUNTY OR FARISH 13. STATE San fina
16. Check Ap	propriate Box To Indicate Nature of Notice, Report	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Spudded well. Drilled surface hole. 03-01-76

ABANDON*

CHANGE PLANS

PULL OR ALTER CASING

MULTIPLE COMPLETE

Ran 5 joints 9 5/8", 32.3#, HS surface casing, 208' set at 222'. Cemented 03 - 02 - 76with 245 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.



RECEIVED

MAR 1 0 1976

U. S. GEOLOGICAL SURVEY FARMINGTON, N. M.

SIGNED SIGNED	TITLE	Drilling Clerk	March 5, 1976
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE _		DATE