(June 1990)

UNITED STATES

| FORM APPROVED | | | | | |
|-----------------------------|--|--|--|--|--|
| Budget Bureau No. 1004-0135 | | | | | |
| Evniros: March 31 1993 | | | | | |

| June 1990) | DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT | Budget Bureau No. 1004-0135 Expires: March 31, 1993 |
|---|--|--|
| Do not use this f | ORY NOTICES AND REPORTS ON WELLS CENTER FOR FOR PERMIT - " for such-proposals OFFICE TAPPLICATION FOR PERMIT - " for such-proposals OFFICE TAPPLICATION FOR PERMIT - " for such-proposals | 5. Lease Designation and Serial No. SF-078385 6. If Indian, Allottee or Tribe Name |
| 1. Type of Weil Oil Gas Weil Weil Other | PECEIVEN COLUMN | 7. If Unit or CA, Agreement Designation |
| | | 8. Well Name and No. |
| 2. Name of Operator AMOCO PRODUCTION C | OMBANY 5 1988 tion | Florance K #29/ |
| 3. Address and Telephone No. | - Can in conclosi | 9. API Well No. |
| , | COLORADO 80201 DIGG 9 | 3004521786 |
| P.O. BOX 800 DENVER, (| | 10. Field and Pool, or Exploratory Area |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Da | scription) | Blanco Mesaverde |
| 1850' FNL 1856 | O'FWL Sec. 25 T 30N R 8W UNITF | 11. County or Parish, State |
| | J1772 | SAN JUAN NEW MEXICO |
| 12. CHECK APPROP | PRIATE BOX(s) TO INDICATE NATURE OF NOTICE, R | EPORT, OR OTHER DATA |
| TYPE OF SUBMISSION | TYPE OF ACTION | |
| Notice of Intent Subsequent Report Final Abandonment Notice | Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other New Tbg Depth (Note: Repor | Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water It results of multiple completion on Well Completion or Recomplation Report and Log for |
| 13. Describe Proposed or Completed Operations (Clearly stamarkers and zones pertinent to this work.)* | te all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilk | led, give subsurface locations and measured and true vertical depths for all |
| MIRUSU 6/26/98. Dig ou | ut bradenhead. No tbg head on well only master valve 4.063. Rig u t 2920' and rig down wireline. | p HES run gauge ring to 3100'. Set |
| Test casing to 500# for a valve and valve head an | 15 minutes. Held okay. Open intermediate and bradenhead with no od remove. | pressure or flow, annuli dead. ND master |
| tog. The to 2920 and an | with secondary packing, NUBOP and relief lines to flow back to tar Il out composite bridge plug. Pick up tbg tag fill in open hole at 442 tion sand. SIFN. SICP 220#. TIH tag fill at 4475' clean out fill to 450 rs. | 0' and clean out to 4479'. Hole tight |
| TIH remove well head, ir | nstall new tbg head to accept new tbg. Cleanout open hole and rela | and new tbg at a new depth of 4378'. |
| SI over night flowed for | | |

SI over night, flowed for 3 hrs at a stable rate of 1.1mmcfd.

RDMOSU 7/2/98.

| 14. I hereby certify (ast 15th foragoing is true and correct Signed Liul CU, Hereby Certify (ast 15th correct) | Title | Sr. Admin. Staff Asst. | Date | 07-08-1998 |
|--|-------------------------|--|-------------------------|--------------|
| (This space for Federal or State office use) Approved by Conditions of approval, if any: | Title | AUCEPT | 0.4 | RECORL |
| Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of t | he United States any fa | dse, ficticious, or fraudulent statements or representations as to eny m | arter within its jurist | 98 Etion. |