

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a dormant reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

USA-SF-080004

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Florance

9. WELL NO.

8A

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

Sec. 14, T30N, R9W

12. COUNTY OR PARISH

San Juan

13. STATE  
New Mexico

1. OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR  
TENNECO OIL COMPANY

3. ADDRESS OF OPERATOR  
1860 Lincoln St., Suite 1200 Denver, CO 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

1450' FSL and 1025' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6042 GL

16.

### Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8/5-8/26/75 - Waiting on completion unit and testing casing.  
8/27 PBDT tagged @ 5195. Perforated Pt. Lookout. @ 4847, 55, 59, 64, 72, 74, 81, 85, 90, 4904, 18, 20, 45, 48, 57, 71, 76, 86, 89, 19 holes. Broke down. Pt. Lookout @ 2600 psi @ 46 bpm. Dropped 27 balls in 19 bbls. 15% HCL. Frac'd with 111,600# 20/40 sand and 2997 bbls of fresh water. AIR 40 bpm at 2000 psi.  
8/28 Set B.P. to 4715. Spot 10' of sand on top. Spotted 500 gallons 15% hydrochloric 4687. Perforated Menefee @ 4687, 83, 78, 45, 42, 34, 32, 25, 22, 4591, 83, 74, 65, 61, 58, 53, 34, 32 18 holes. Broke down Menefee w/2450 psi, 42 bpm, Dropped 27 ball sealers in 12 bbls of 15% hydrochloric & 19 bbls of 3% hydrofloric. Frac'd with 110,400 # 20/40 sand and 2997 bbl of fresh water. AIR 41 bpm @ 2000 psi.

SEP 8 1975

U.S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct

SIGNED

*Paul F. Drake*

TITLE Production Clerk

DATE 9/4/75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side