DEC 22 1997

Meter Number:95287
Location Name:FLORANCE 8A FT
Location:TN-30 RG-09
SC-14 UL-I
2 - Federal
NMOCD Zone:OUTSIDE
Hazard Ranking Score:00

DECEIVED APR 1 4 1997 OIL GON. DAV.

RATIONAL FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



## FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 45287 Location: Florence &A FT  Operator #: 0207 Operator Name: Ameca P/L District: 6100mfie//  Coordinates: Letter: L Section 14 Township: 30 Range: 9  Or Latitude Longitude  Pit Type: Dehydrator Location Drip: \( \sum \) Line Drip: Other:  Site Assessment Date: \( \frac{1}{2} \) Area: 10 Run: \( \frac{3}{2} \)							
SITE ASSESSMENT	NMOCD Zone:  (From NMOCD  Maps)  Inside  Outside  Outsid							
S	Remarks: Jpits. Pit Dry. Only lpit will be pushed in.							
REMAKAS	- The state of the pushed in.							
EM								
Щ	1 AUSH IN 194/08/94							

	ORIGINAL PIT LOCATION					
Z	Original Pit : a) Degrees from North <u>198°</u> Footage from Wellhead <u>61'</u> b) Length : <u>20'</u> Width : <u>20'</u> Depth : <u>4'</u>					
ORIGINAL PIT LOCATION	Wellhead 1980					
	Remarks: Pictures taken at 200 pm End Dump					
REMARKS						
	Completed By:					
	Con Clane 4/25/94					

` [	
GEI. RAL	Meter: 95282 Location: Florence 8A FT  Coordinates: Letter: I Section 14 Township: 30 Range: 9  Or Latitude Longitude  Date Started: 5-18-94 Area: 10 Run: 33
FIELD OBSERVATIONS	Sample Number(s): \( \subseteq \overline{\subsete} \) Feet  Sample Depth: \( \subseteq \overline{\subsete} \) Feet  Final PID Reading \( \overline{\subsete} \) O PID Reading Depth \( \overline{\subsete} \) Feet  Yes No  Groundwater Encountered \( \overline{\subsete} \) (1) \( \overline{\subsete} \) Approximate Depth \( \overline{\subsete} \) Feet
CLOSURE	Remediation Method:  Excavation
REMARKS	Remarks: Line markers  Signature of Specialist: Vale Wilson

(SP3191) 04/07/94



## FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

## SAMPLE IDENTIFICATION

					·	
	Field ID			Lab ID		
SAMPLE NUMBER:		VW 108		945229		
MTR CODE   SITE NAME:		287	N/A			
SAMPLE DATE   TIME (Hrs):	5-18-94		1420			
SAMPLED BY:		N/A				
DATE OF TPH EXT.   ANAL.:	5-	5-19-94		5/19/94		
DATE OF BTEX EXT.   ANAL.:		NIA		NIA		
TYPE   DESCRIPTION:	VG		Frown (	Brown Course Sand		
		RESULTS				
PARAMETER	RESULT	UNITS	NITS QUALIFIER QUALIFIER	QUALIFIERS  DF Q M(g)		g) V(ml)
BENZENE		MG/KG			ivitg)	V (1111
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG		· · · · · · · · · · · · · · · · · · ·		
TOTAL BTEX		MG/KG				
TPH (418.1)	<10	MG/KG			2.22	28
HEADSPACE PID	£ 10.0	JUN 812 19V				

- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

PERCENT SOLIDS

The Surrogate Recovery was at Narrative:	<u> </u>	% for this sample	All QA/QC was acceptable.		
DF = Dilution Factor Used		1.00			
~ D	$\mathcal{L}$		Meday		

Test Method for Oil and Grease and Petroleum Hydrocarbons in Water and Soil

Perkin-Elmer Model 1600 FT-IR Analysis Report \*

04/05/19 14:03

Sample identification

Initial mass of sample, g

Volume of sample after extraction, ml 73.000

Petroleum hydrocarbons, ppm 310.538 Net absorbance of hidrocarbons (2930 cm-1) -0.06€



