

80801

District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211
District III
100 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

OK
no tests
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

PIT REMEDIATION AND CLOSURE REPORT

Operator: Amoco Production Company Telephone: (505) - 326-9200
Address: 200 Amoco Court, Farmington, New Mexico 87401
Facility Or: ELLIOT GC F #1R
Well Name
Location: Unit or Qtr/Qtr Sec 8 Sec 33 T 30N R 9W County SAN JUAN
Pit Type: ^{ABANDONED} Separator ☒ Dehydrator ☐ Other ☐
Land Type: BLM ☐, State ☐, Fee ☒, Other ☐

Pit Location: Pit dimensions: length NA, width NA, depth NA
(Attach diagram) Reference: wellhead ☒, other ☐
Footage from reference: 147'
Direction from reference: 29 Degrees ☒ East North ☒
of
West South ☐

Depth To Ground Water: Less than 50 feet (20 points)
(Vertical distance from 50 feet to 99 feet (10 points)
contaminants to seasonal Greater than 100 feet (0 Points) 0
high water elevation of
ground water)

Wellhead Protection Area: Yes (20 points) 0
(Less than 200 feet from a private No (0 points) 0
domestic water source, or; less than
1000 feet from all other water sources)

Distance To Surface Water: Less than 200 feet (20 points)
(Horizontal distance to perennial 200 feet to 1000 feet (10 points) 0
lakes, ponds, rivers, streams, creeks, Greater than 1000 feet (0 points) 0
irrigation canals and ditches)

RANKING SCORE (TOTAL POINTS): 0

85801

ABAN. SEP. PIT

Date Remediation Started: _____ Date Completed: 10/24/00Remediation Method: Excavation ☒ Approx. cubic yards NA
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____Other CLOSE AS ISRemediation Location: Onsite ☒ Offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description of Remedial Action: _____

Excavation, NO REMEDIATION NECESSARY.

Ground Water Encountered: No ☒ Yes _____ Depth _____Final Pit: Sample location see Attached DocumentsClosure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)Sample depth 8' (TEST HOLE BOTTOM)Sample date 10/20/00 Sample time 0915

Sample Results

Benzene(ppm) _____

Total BTEX(ppm) _____

Field headspace(ppm) 0.0TPH NDGround Water Sample: Yes _____ No ☒ (If yes, attach sample results)I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST
OF MY KNOWLEDGE AND BELIEFDATE 10/24/00
SIGNATURE B. Shaw PRINTED NAME AND TITLE Buddy D. Shaw
ENVIRONMENTAL COORDINATOR

CLIENT: <u>AMOCO</u>	BLAGG ENGINEERING, INC. P.O. BOX 87, BLOOMFIELD, NM 87413 (505) 632-1199	LOCATION NO: <u>80801</u> C.O.C. NO: <u>8247</u>
----------------------	--	---

FIELD REPORT: CLOSURE VERIFICATION	PAGE No: <u>1</u> of <u>1</u>
------------------------------------	-------------------------------

LOCATION: NAME: <u>ELLIOTT GC</u> F WELL #: <u>1R</u> PIT: <u>ABAND. SEP.</u> QUAD/UNIT: <u>B</u> SEC: <u>33</u> TWP: <u>30N</u> RNG: <u>9W</u> PM: <u>NM</u> CNTY: <u>ST</u> ST: <u>Nm</u> QTR/FOOTAGE: <u>810N/1590E</u> <u>NWNE</u> CONTRACTOR: <u>FLINT</u>	DATE STARTED: <u>10/20/00</u> DATE FINISHED: _____ ENVIRONMENTAL SPECIALIST: <u>NV</u>
---	--

EXCAVATION APPROX. <u>NA</u> FT. x <u>NA</u> FT. x <u>NA</u> FT. DEEP. CUBIC YARDAGE: <u>NA</u>	DISPOSAL FACILITY: <u>02-SITE</u> REMEDIATION METHOD: <u>CLOSE AS IS</u>	LAND USE: <u>RANGE</u> LEASE: <u>FEE</u> <u>CA SW1056</u> FORMATION: <u>MV</u> <u>SE-078139</u>
---	--	--

FIELD NOTES & REMARKS:	PIT LOCATED APPROXIMATELY <u>147</u> FT. <u>N29E</u> FROM WELLHEAD. DEPTH TO GROUNDWATER: <u>>100'</u> NEAREST WATER SOURCE: <u>>1000'</u> NEAREST SURFACE WATER: <u>>1000'</u> NMCD RANKING SCORE: <u>0</u> NMCD TPH CLOSURE STD: <u>5000</u> PPM <u>SOIL AND EXCAVATION DESCRIPTION:</u>
------------------------	--

CHECK ONE :
☒ PIT ABANDONED
☐ STEEL TANK INSTALLED
☐ FIBERGLASS TANK INSTALLED

OK. YELL. BROWN SAND, NON COHESIVE, SLIGHTLY MOIST, FIRM, NO APPARENT DISCOLORATION OBSERVED OR HC POCOR DETECTED WITHIN TEST HOLE OR DUM SAMPLE.

SCALE

0 FT

FIELD 4181 CALCULATIONS

TIME	SAMPLE I.D.	LAB No:	WEIGHT (g)	mL. FREON	DILUTION	READING	CALC. ppm
0915							

PIT PERIMETER

PIT DEPRESSION

APPROX. 3' BELOW GRADE

OVM RESULTS

SAMPLE ID	FIELD HEADSPACE PID (ppm)
1 @ 8'	0.0
2 @	
3 @	
4 @	
5 @	

PIT PROFILE

NOT APPLICABLE

LAB SAMPLES

SAMPLE ID	ANALYSIS	TIME
DE 8'	TPH (8015)	0915

TRAVEL NOTES: CALLOUT: 10/19/00 - AFTER. ONSITE: 10/20/00 - MOR.

EPA METHOD 8015 Modified
Nonhalogenated Volatile Organics
Total Petroleum Hydrocarbons


Client:	Blagg / BP	Project #:	403410
Sample ID:	1 @ 8'	Date Reported:	10-24-00
Laboratory Number:	18430	Date Sampled:	10-20-00
Chain of Custody No:	8247	Date Received:	10-20-00
Sample Matrix:	Soil	Date Extracted:	10-23-00
Preservative:	Cool	Date Analyzed:	10-24-00
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.1

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: Elliott GC F #1R Abandoned Separator Pit.


Analyst


Review

CHAIN OF CUSTODY RECORD

0824.

Client / Project Name		Project Location		ANALYSIS / PARAMETERS									
BAGG / BP		ELLUOT GC F #1R											
Sampler: NJV		Client No. 403410											
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers	TPH (80/15)							Remarks
De 7'	10/20/00	0855	18429	SOIL	1	✓							ABANDONED ROW PIT
De 8'	10/20/00	0915	18430	SOIL	1	✓							ABANDONED SEPARATOR PIT
De 8'	10/20/00	0940	18431	SOIL	1	✓							ABANDONED DEHYDRATOR PIT
													ALL SAMPLES
													PRESERV. - COOL
Relinquished by: (Signature)		Date		Time		Received by: (Signature)		Date		Time			
[Signature]		10/20/00		1358		[Signature]		10/24/00		1358			
Relinquished by: (Signature)						Received by: (Signature)							
Relinquished by: (Signature)						Received by: (Signature)							
ENVIROTECH INC. 5796 U.S. Highway 64 Farmington, New Mexico 87401 (505) 632-0615													Sample Receipt Y N N/A Received Intact Cool - Ice/Blue Ice