UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5. LEASE 🕺 🛱 🖁		ై ద్రీ
SF_078336 C \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	(a)	<u> </u>
6. IF INDIAN, ALLOT	TEE OR TRIE	BE NAN

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	<u> </u>
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	9 FARM OR LEAST MANE
1 all ——————————————————————————————————	8. FARM OR LEASE NAME A PARTY OF THE LINDS O
1. oil gas ⊠ other	9. WELL NO. 2 6
2. NAME OF OPERATOR	2A 95 6 5 0 8 5
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco M.V.
P.O. Box 289, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 11, T-30-N, R-9-W
below.) AT SURFACE: 1750'S, 1750'E	N.M. P.M. 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14 ADLNO
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. AFINO. 25421 2 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5954' GL종종원의 - 월 교육교교
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	The Court of the second of the court of the
CHANGE ZONES	
ABANDON*	
(Onter)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat	e all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and int to this work.)* 1 2 2 2 2
12-30-78: TD 3070'. Ran 79 jts. 7", 20#, K-55	intermediate casing 30501 set at
3070'. Cemented w/361 cu. ft. cement. WOC 12 h	
of cement at 1300'.	
	W EE
1-03-79: TD 5412'. Ran 78 jts. 4 1/2", 10.5#, 5412'. Float collar set at 5396'. Cemented w/4	
•	
4-14-79: PBTD 5396'. Tested casing to 3500#, O	
4873,4893,4964,4973,4980,4986,4992,4999,5006,501	
5146,5200,5231,5250,5266,5277,5299,5368' w/1 SPZ 183,000 gal. water. Flushed w/6720 gal. water.	
4398,4425,4442,4470,4492,4498,4504,4510,4516,453	
4689,4695,4713,4739,4746' w/1 SPZ. Fraced w/84,	
water. Flushed w/6720 gal. water.	දිරිමුණියු සිංහු සිංකුකිදි
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	The state of the s
M M Region Doilling Cla	mlc Anni 1 9 7 9 10 700 9 3
SIGNED A TITLE DITITING CIE	rk DATE April 17, 1979
(This page for Endays) or State off	and the second s

(This space for Federal or State office use)

APPROVED BY ______ TITLE ______ TITLE _____

3.30

DATE TO SERVICE OF THE PARTY OF

ten a litera

PIL CON. COM. DIST. 3

*See Instructions on Reverse Side

MYMOCC