	<b>\</b>			
Form 9-331 (Mny 1963)	DEPART	SEOLOGICAL SURVEY		Form approved. Budget Bureau No. 42-R1424.  5. Leane Designation and Berial No.  SF - 080005  6. If Indian, Allottee or Tribe Name
S (Do not use	UNDRY NOT	ICES AND REPORT	SON WELLS  blug back to a different reservoir.  uch proposals.)	7. UNIT AGREEMENT NAME
OIL GA	S OTHER	8. FARM OR LEASE NAME		
	eco Oil Comp	Florance 9. WELL NO.		
3. ADDRESS OF OPE  1860 4. LOCATION OF WE See also spuce 1 At surface	Lincoln St.	Blanco Mesa Verde		
		L and 1450' FEL. it o		Sec. 23, T30N, R90
14. PERMIT NO.		15. ELEVATIONS (Show when		San Juan New Mexic
TEST WATER S FRACTURE THE SHOOT OR ACH REPAIR WELL (Other)  17. DESCRIBE PROPER proposed we nent to this	NOTICE OF INTE	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS  PERATIONS (Clearly state all p	WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING ON ACIDIZING  (Other)  (NOTE: Report rest Completion or Reco ertinent details, and give pertinent da ce locations and measured and true ver	ALTERING WELL  ALTERING CASING  ABANDONMENT®  Alter of multiple completion on Well  mpletion Report and Log form.)  tes, including estimated date of starting any tical depths for all markers and zones perti-
10/17	- 10/25/76:	with 565 sacks o Drilled 6-1/8" h	f cement. Circulated di ole to 5049' TD. Ran lo r from 2663' - 5049' wi aited on cement. Prese	th 200 sacks of cement.

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Div. Production Manager	DATE 18 18 18
(This space for Federal or State office use)		DATE
APPROVED BY	TITLE	DATE