K OF OPIES RECEIVED	19-1			/ Form C-	
DISTRIBUTION				Supersed C-102 a	nd C-103
SANTA FE		NEW MEXICO OIL CON	SERVATION COMMISSION	Effectiv	• 1-1-65
U.S.G.S.	1 -			5g. Indicate	Type of Lease
LAND OFFICE				State	Fee X
OPERATOR	4			<u> </u>	& Gas Lease No.
OFERATOR	171	i			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
l. OIL GAS	[]			7. Unit Agre	eement Name
well well 2. Name of Operator	x	OTHER-		8 Form or I	_ease Name
Manana Gas, Inc.					ry Wheeler
3. Address of Operator					Ty Wheeler
P.O. Box 80068, Albuquerque, NM 87108					
4. Location of Well				10. Field on	nd Pool, or Wildcat
UNIT LETTERD		1095 FEET FROM THE north	LINE AND 875 F	Ba:	sin Dakota
THE west	INE, SECTIO	DN 23 TOWNSHIP 30]	NRANGE12W	_ NMPM.	
	m			12. County	711/1/////
15. Elevation (Show whether DF, RT, GR, etc.) 5530 KB					uan (())
16.	Check A	Appropriate Box To Indicate N	Nature of Notice, Report	or Other Data	
NOTIC	E OF IN	ITENTION TO:	SUBSE	QUENT REPORT	OF:
	1	<u> </u>			
PERFORM REMEDIAL WORK]	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS.	75	LUG AND ABANDONMENT
PULL OR ALTER CASING	ĺ	CHANGE PLANS	CASING TEST AND CEMENT JOB		LUG AND ABANDONMENT
-	•		OTHER		
OTHER					
17 Describe Proposed or Con	noleted On	perations (Clearly state all pertinent det	ails, and give pertinent dates, i	ncluding estimated day	e of starting any proposed
work) SEE RULE 1103.					
		1/2" csg, 10.5#, K-55 " w/6.5% Gilsonite & 6			
		1.3 hrs. Ran 250 sx Ha	_		
		. Opnd DV tool @ 1967			
Plug dwn bain. Go Pam. Gd circ.	u circ.	• Opind DV tool @ 1907	& cemented w/125	SX W/12/0 Ge	1. Find down
	un 3 7	/8" bit & Baker csg sci	raner. Drld DV to	ols @ 1925 &	4570. Cleaned out
		to 3000 psi. OK. Test			
		000 gals. Spotted 200 g		011, 215,11	
-28-77 Perf'd	6272-7	74, 6282, 6292-94, 6310	0, 6323-28, 6332-4	6, 6355-57,	6383-85, 6398,
		holes. Pumped 1300			
		tr pr 3200#. Bled balls	•		
_		sd. Avg tr pr 2500#.	-	_	-
•		@ 33,000 gals w/250 ps	_	~ ,	
		350psi, 15 min-1000ps			· · · · · · · · · · · · · · · · · · ·
-		hole w/tbg. Tagged fr	-	_	
		menced swabbing @ noo			_
•		8 hrs to clean-up.			٠, ٠
-30-77 Well on	7-day	shut-in test. 24 hr SI above is true and complete to the best	P - 1425 psi.		
18. I hereby certify that the in	nformation	above is true and complete to the best	of my knowledge and belief.		
SIGNED THE		TITLE V	ice-President	DATE	February 7, 1977
	1				
Original Signed by	7 A. R.		urm 15dr - 18t. /s/s	DATE	
CONDITIONS OF APPROVAL	, IF ANY:		**************************************		,
			\$		ţ.