

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-2757-3	
7. Unit Agreement Name	
8. Farm or Lease Name	
Turner B Com	
9. Well No.	
1-A	
10. Field and Pool, or Wildcat	
Blanco Mesa Verde	
12. County	
San Juan	

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	2. Name of Operator
	El Paso Natural Gas Company
3. Address of Operator	
	P. O. Box 289, Farmington, New Mexico 87401
4. Location of Well	
UNIT LETTER <u>F</u> , <u>1830</u> FEET FROM THE <u>N</u> LINE AND <u>1548</u> FEET FROM	
THE <u>W</u> LINE, SECTION <u>2</u> TOWNSHIP <u>30N</u> RANGE <u>9W</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
6018' GR	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>		
OTHER	<input checked="" type="checkbox"/>	Replace sucker rod pump	<input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-16-80 Pulled pump and changed out same. Did not pull tubing. Tubing is 2 3/8" EUE 5332', set at 5342'. A mechanical bottom hold-down was run on the bottom of the pump. It is set at 5284'. Ran (139) 5/8" and (70) 3/4" rods.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.B. Grant TITLE Production Engineer DATE 8-20-80

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT #3

APPROVED BY _____ TITLE _____ DATE AUG 25 1980

CONDITIONS OF APPROVAL, IF ANY: