

[illegible]

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR
OR FOR A PROPOSAL FOR PERMITTING SUCH PROPOSALS.

1. NAME OF OPERATOR EL PASO NATURAL GAS CO. 2. ADDRESS OF OPERATOR BOX 990, FARMINGTON, NEW MEXICO 87401 3. LOCATION OF WELL (Refer to the clearly and in accordance with any State requirements. See also space 17 below.) At surface 1740'N 181°W 4. PERMIT NO. 5. ELEVATIONS (Show whether DE, RE, GR, etc.) 6524' GR 6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2">NOTICE OF INTENTION TO:</th> <th colspan="2">CURRENT OR FORMER</th> </tr> </thead> <tbody> <tr> <td>TEST WATER SHUT-OFF</td> <td>TELL OR ALTER CASING</td> <td>WATER SHUT-OFF</td> <td>REPAIR CASING</td> </tr> <tr> <td>CRACK RE-TREAT</td> <td>MULTIPLE COMPLETION</td> <td>CRACK RE-TREATMENT</td> <td>REPAIR CASING</td> </tr> <tr> <td>SHOOT OR ACIDIZE</td> <td>FRAC TON*</td> <td>SIGHTON COMPLETION</td> <td>REPAIR CASING*</td> </tr> <tr> <td>REPAIR WELL</td> <td>CHANGE PLANS</td> <td>OTHER</td> <td></td> </tr> </tbody> </table> (Other)	NOTICE OF INTENTION TO:		CURRENT OR FORMER		TEST WATER SHUT-OFF	TELL OR ALTER CASING	WATER SHUT-OFF	REPAIR CASING	CRACK RE-TREAT	MULTIPLE COMPLETION	CRACK RE-TREATMENT	REPAIR CASING	SHOOT OR ACIDIZE	FRAC TON*	SIGHTON COMPLETION	REPAIR CASING*	REPAIR WELL	CHANGE PLANS	OTHER		7. DATE OF NOTICE 11/1/77 8. TYPE OF NOTICE PRELIMINARY 9. WELL NO. 15, T-29-N, 10-B 10. WELL NAME SAN JOSE MESA VERDE 11. WELL LOCATION 15, T-29-N, 10-B 12. WELL TYPE OIL 13. WELL STATUS NEW 14. WELL DEPTH 6524' 15. WELL TYPE OIL 16. WELL STATUS NEW 17. WELL TYPE OIL
NOTICE OF INTENTION TO:		CURRENT OR FORMER																			
TEST WATER SHUT-OFF	TELL OR ALTER CASING	WATER SHUT-OFF	REPAIR CASING																		
CRACK RE-TREAT	MULTIPLE COMPLETION	CRACK RE-TREATMENT	REPAIR CASING																		
SHOOT OR ACIDIZE	FRAC TON*	SIGHTON COMPLETION	REPAIR CASING*																		
REPAIR WELL	CHANGE PLANS	OTHER																			

11/5/77: Spudded well. Drilled surface hole. Ran 5 joints of 2" x 31.3% 12-3 surface casing, 215' set at 248'. Cemented with 224 cu. yd. cement. Circulate to surface. WOC 12 hours; held 600#/50 minutes.

18. I hereby certify that the foregoing log is true and correct.

SIGNED *[Signature]*

title: Drilling Clerk

DATE 11/2/75

(Leave blank)
(This space for Federal or State office use)

APPROVED BY

TITLES

1. *Journal of the American Medical Association*, 1997; 277: 1033-1037.

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 8 1977

*See Instructions on Reverse Side

U.S. Geological Survey
Farmington, N.M.