## **UNITED STATES**

18. I hereby certify that the foregoing is true and correct

UNITED STATES  DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE NM 03202  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME San, Juan
1. oil gas well other  2. NAME OF OPERATOR	San Juan 200 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
El Paso Natural Gas Company  3. ADDRESS OF OPERATOR P. O. Box 990, Farmington, New Mexico 87401	Blanco Mesa Verde  11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 950' N, 1800' W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 10, T-30-N, R-10-W NMPM  12. COUNTY OR PARISH San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.  15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO:  SUBSEQUENT REPORT OF:  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE  CHANGE ZONES  ABANDON*  (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.):
<ul> <li>17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent</li> <li>12-26-77 Spudded well. Drilled surface hole Ran 5 joints 9 5/8", 32.3#, H-40 states</li> </ul>	t to this work.)*
Cemented with 224 cu. ft. cement. 12 hours; held 600#/30 minutes.  Subsurface Safety Valve: Manu. and Type	
Dabbarrade Carety restor manarana 13po	

TITLE Drilling Clerk

(This space for Federal or State office use)

\_\_\_ TITLE \_\_\_

DATE