

6 BLM

1 File

Form 9-331
Dec. 1973

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐2. NAME OF OPERATOR
DUGAN PRODUCTION CORP.3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 874994. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
790' FSL - 1850' FWL
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input checked="" type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input checked="" type="checkbox"/>
(other) Ready for BLM Inspection	

5. LEASE
NM 030555A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Dare Devil

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Wildcat

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
Section 10 T30N R13W, NMPM

12. COUNTY OR PARISH
San Juan

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5702' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The #1 Dare Devil was plugged as per BLM Stipulations, recorded on Sundry Notice dated 8-6-82. The surface rehabilitation requirements necessary for permanent abandonment have been accomplished as required by BLM letter 3100 (016), dated 8-9-84. The location is now ready for BLM inspection.

RECEIVED

SEP 18 1984

OIL COM.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct.

SIGNED Sherman E. Dugan TITLE Geologist DATE _____

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:**ACCEPTED FOR RECORD**

SEP 14 1984

FARMINGTON RESOURCE AREA

BY SWT