gas

well

XX

DUGAN PRODUCTION CORP.

Form 9-331 Dec. 1973

well

2. NAME OF OPERATOR

AT SURFACE:

FRACTURE TREAT SHOOT OR ACIDIZE

REPAIR WELL

ABANDON* (other)

AT TOTAL DEPTH:

3. ADDRESS OF OPERATOR

AT TOP PROD. INTERVAL:

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

other

P O Box 208, Farmington, NM 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,

1590' FNL - 790' FEL

l File	Form Approved. Budget Bureau No. 42-R1424
,	5. LEASE
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
N WELLS	7. UNIT AGREEMENT NAME-
back to a different	8. FARM OR LEASE NAME 를 프로그램 Molly Pitcher - 를 모르고
	9. WELL NO. 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	Wilded I
37499 Y. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14 T30N RI4W
L	12. COUNTY OR PARISH 13. STATE NM -
RE OF NOTICE,	14. API NO.
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5950' GL
REPORT OF	ELVED
SEPS	
BURBAU ON LAS MINOTONIO	्ट े(NOTE::सिवport)résults of multiple completion or zon ெல்லே ' இரை கள்தல், on Form 9–330.)
Ready for B	LM Inspection

3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSEQUENT REPORT OF

The #2 Molly Pitcher was plugged and abandoned on 9-11-84 per BLMs tipulations as follows:

1	Filled 2-7/8" OD, 6.4#, CW-55 NEUE tubing for casing from PBTD	1778'
	to surface using 49 sx class "B" heat cement.	
2.	Installed permanent dry hole monument.	7. 4
_		
4.	Cleaned well location of all equipment, pipe, junk and trash.	

5. Restored surface per surface management agency guidelines. 6. Removed tie-downs.

6. Removed tie-downs.	TESTS OF COM
The location is now ready for BLM inspection.	books and a state of the control of
Subsurface Safety Valve: Manu. and Type	Set W
18. I hereby certify that the foregoing is true and correct Geologist DATE	3.7 mg 2 mg
SIGNED Sherman E. Dugas Geologist DATE	

(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: