6 - USGS, Fmn

Form 9-331

1 NWPL

1 File

Form Approved. Budget Bureau No. 42-R1424

Dec. 1973 UNITED STATES 5. LEASE NM 0206994 DEPARTMENT OF THE INTERIOR 6. IF INDIAN, ALLOTTEE OR TRIBE NAME GEOLOGICAL SURVEY 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 8. FARM OR LEASE NAME Carpenter 1. oil gas well Dry hole other 9. WELL NO. well 2. NAME OF OPERATOR 10. FIELD OR WILDCAT NAME DUGAN PRODUCTION CORP. Harper Hill 3. ADDRESS OF OPERATOR 11. SEC., T., R., M., OR BLK. AND SURVEY OR P O Box 208, Farmington, NM 87401 AREA 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 Sec 25 T30N R14W below.) 1460' FSL - 1850' FWL 12. COUNTY OR PARISH 13. STATE AT SURFACE: <u>San Juan ^{ta v}</u> AT TOP PROD. INTERVAL: NM AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) <u>5500</u>' GL[⊆] SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* Restoration & Reseeding (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Pits filled and location recontoured. Equipment removed. Reseeded with seed mix #3 7-14-82. P & A marker installed. JUL 7-1983 Location ready for inspection. Subsurface Safety Valve: Manu. and Type ___ fy that the focegoing is true and correct 7-20-82 Agent DATE

Dugan

TITLE .

(This space for Federal or State office use)

__ DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY