
MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other)

## DEPART GE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 078438 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 32-9 Unit 8. FARM OR LEASE NAME
1. oil gas well other  2. NAME OF OPERATOR	San Juan 32-9 Unit  9. WELL NO. 20A
EL PASO NATURAL GAS CO.  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME BLANCO M.V.
BOX 990, FARMINGTON, NEW MEXICO  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18, T-31-N, R-9-W NMPM
AT SURFACE: 1550'S, 1155'E AT TOP PROD. INTERVAL: AT TOTAL CEPTH:	12. COUNTY OR PARISH 13. STATE  SAN JUAN NEW MEXICO  14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF	6542' GL
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5/29/78: Spudded we 1. Drilled surface hole. Ran 5 joints 9 5/8", 36# K-55 surface casing, 207' set at 220'. Cemented with 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.



desir.

Subsurface Safety Valve: Manu. and Type \_\_\_ 18. I hereby certify that the foregoing is true and correct Drilling Clerk DATE

(This space for Federal or State office use)

\_ TITLE

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: DATE