

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1421.

5. LEASE DESIGNATION AND SERIAL NO.

SF 079082

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Northeast Blanco Unit
Agreement No. 1, Sec. 929

8. FARM OR LEASE NAME

Northeast Blanco Unit

9. WELL NO.

66A

10. FIELD AND POOL, OR WILDCAT

Blanco Mesaverde

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

31

E-31N-7W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Blackwood & Nichols Co., Ltd.

3. ADDRESS OF OPERATOR

P.O. Box 1237 Durango, Colorado 81301

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2100' F/NL - 300' F/WL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6422' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Casing & Cement ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*5-30-78 Spud surface hole at 6:30 PM, 5-29-79; ran 5 jts, 9 5/8" 36#, Grade H, casing;
209' set at 221' KB; cemented with 200 sacks of Class B cement with 1/4# Flocele
and 2% CaCl₂. Tested casing for thirty with 800 PSI, held OK.6-4-78 Ran 92 jts 7" 23# Grade K casing; 3633' set at 3645' with 200 sacks Howco Lite
with 1/4# Flocele/sack and 100 sacks of Class B with 2% Cacl₂ and 1/4# Flocele
per sack. Ran temperature survey after eight hours, top of cement at 1200'.
Tested casing to 1000 PSI, held OK.6-7-78 Ran 61 jts, 4 1/2" 10.50# K-55 casing; 2561' set at 6035'; float collar at 5999';
top of liner at 3474'. Cemented with 300 sacks of 50-50 Poz mix with 2% Gel,
0.6% FLA, 6 1/4# Gilsonite per sack and 1/4# Flocele per sack. Reversed out
16 bbls of cement.

18. I hereby certify that the foregoing is true and correct

SIGNED Delasso Loos

TITLE District Manager

DATE 6-9-78

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

RECEIVED
DATE

JUN 12 1978

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.