

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 079082

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Blackwood & Nichols Co., Ltd.

3. ADDRESS OF OPERATOR
P.O. Box 1237, Durango, Colorado 81301

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2100' F/NL - 300' F/WL

7. UNIT AGREEMENT NAME
Northeast Blanco Unit
Agrmt. No. 1, Sec. 929

8. FARM OR LEASE NAME
Northeast Blanco Unit

9. WELL NO.

66A

10. FIELD AND POOL, OR WILDCAT

Blanco Mesaverde

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

E-31-31N-7W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6422' GL

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☒

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-16-78 Perforated first stage, four holes/interval, 5640', 5650', 5656', 5670', 5680', 5714', 5738', 5768', 5808', 5826' and 5876'. Sand-water fractured with 95,372 gallons water with 2# FR-20/1000 gallons and 80,000# of 20-40 sand. Maximum pressure 1900 PSI, average pressure 1500 PSI, average injection rate 58 bbls/min. Set top drillable bridge plug at 5620'.

7-17-78 Perforated second stage four holes/interval; 5260', 5280', 5290', 5298', 5308', 5360', 5380', 5440', 5590' 5600' and 5610'. Sand-water fractured with 72,630 gals. water with 2# FR-20/1000 gallons and 55,000# of 20-40 sand. Maximum pressure 1750 PSI, average pressure 1000 PSI, average injection rate 62 bbls/min.

18. I hereby certify that the foregoing is true and correct

SIGNATURE DeLasso Loos

TITLE District Manager

DATE 7-17-78

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 18 1978

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.