
MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 077730 6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME			
1. oil gas well other 2. NAME OF OPERATOR	Sunray E 9. WELL NO. 1A			
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco M.V.			
P.O. Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T-30-N, R-10-W N.M.P.M.			
AT SURFACE: 880'S, 1470'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE San Juan New Mexico 14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-17-79: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 36#, KS surface casing, 201' set at 213'. Cemented w/224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.



Subsurface Safety Valve: Manu. and Type		U. S. GE	MINGTON, N. Set @	F
18. I hereby certify that the foregoing is t	rue and correct			
SIGNED A BUSED	TITLEDrilling Clerk	DATE	March 19, 1979	_
	(This space for Federal or State office use)	1		-
APPROVED BY	TITLE	DATE		_

*See Instructions on Reverse Side