

6 BLM

1 NWPL. Randolph

2 El Paso

1 File Form Approved.

Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☐ well other ☒ Dry Hole2. NAME OF OPERATOR
DUGAN PRODUCTION CORP.3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 874994. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 790' FNL - 1850' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) _____

SUBSEQUENT REPORT OF:

☐ RECEIVED
☐ SEP 24 1984
☐ BUREAU OF LAND MANAGEMENT
☐ FARMINGTON RESOURCE AREA
☒ Ready for BLM Inspection

5. LEASE

NM 10561

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Big Field

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

Wildcat FF

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 3 T30N R14W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

5662' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

OCT 01 1984

OIL CON. DIV.
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The #2 Big Field was plugged on 9-11-84 as per BLM stipulations as follows:

1. Filled 2-7/8" OD, 6.4#, CW-55, 10 Rd. reg. tubing for casing from PBTD 1275' to surface using 35 sx class "B" neat cement.
2. Installed permanent dry hole monument.
3. Filled all pits.
4. Cleaned well location of all equipment, pipe, junk and trash.
5. Restored surface per surface management agency guidelines.
6. Removed tie-downs.

The location is now ready for BLM inspection.

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan TITLE GeologistDATE 9-21-84

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: