

4-USGS (Farmington) 1-EPNG (Fields, El Paso) 1-NWP (Randolph) 1-File

Form 9-331
Dec. 1973

Form Approved.

Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
Dugan Production Corp.

3. ADDRESS OF OPERATOR
Box 208, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 800' FNL - 960' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) tbg

☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE

NM 024158

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

McKenzie

9. WELL NO.

#1E

10. FIELD OR WILDCAT NAME

Basin Dakota

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

Sec 20 T30N R12W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5792' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

OCT 03 1979

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-18-79

Opened csg @ 6:00 a.m. and established good water return. Ran 1-1/2" EUE tbg and tagged sand @ 6548'. Hooked up pump and reverse circulated to 6580'. Lost about 10 bbl of water from pit into well. When pump was shut off well kept kicking fluid and sand. Two joints were pulled and landed 202 jts 1-1/2" 2.9# 10R EUE tbg. TE 6537.30' set @ 6546' RKB. BOP was removed and wellhead nipped up. Shut in csg and tbg opened. Blowing good @ 6:30 p.m. Moved from location.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dugan TITLE Petro. Eng.

DATE 10-2-79

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

