REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES

FRACTURE TREAT SHOOT OR ACIDIZE

REPAIR WELL

ABANDON\*

A STATE OF

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Dec. 1973	Budget Bureau No. 42-R1424	
UNITED STATES  DEPARTMENT OF THE INTERIOR	5. LEASE SF-078998	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	San Juan 32-7 Unit	
4 "	San Juan 32–7 Unit	
weil Well & other	9. WELL NO. 10 10 10 10 10 10 10 10 10 10 10 10 10	
2. NAME OF OPERATOR		
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME So Los Pinios Fruitland, Pictured Cliffs	
3. ADDRESS OF OPERATOR		
P.O. Box 90, Farmington, New Mexico 87041	11. SEC., T., R., M., OR, BLK. AND SURVEY OR AREA 교육 경험 용 등 등 교육	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec 9 T31N 2 17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
AT SURFACE: 1010' FNL & 1590' FEL	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	San Juan New Mexico	
AT TOTAL DEPTH:	14. API NO. 3555 2 9.555	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	30-045-23614 開幕 東京電影	
	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
PEOUEST FOR APPROVAL TO: SUBSECUENT PEPOPT OF	6739 5 GR 7 8 9 8 9	

50

bhar

Bacitalego Bedrioore Bedrioore Bedrioore

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

5

DATE

ni blugdal o srab (for o bouton o all bar

go Haw of the grising (other) Drlg Operations 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 45 THE

Mar 13, to 19, 1980 Drlg 6-3/4" hole w/water & gel.

Mar 19, 1980 Drld 6-3/4" hole to 3835' (TD). Ran IES & Neutron Density/GR logs. Ran 128 jts (3831') 2-7/8", 6.4#, J-55, EUE csg set

SUBSEQUENT REPORT OF:

NOW WAITING ON COMPLETION.

	To Describe the second
Subsurface Safety Valve: Manu. and Type	Set @Ft
18. I hereby certify that the foregoing is true and correct	10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

ACCEPTED FOR RECORD

(This space for Federal or State office use)

Production Clerk DATE

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

MAR 25 '80

DISTRICT

\*See Instructions on Reverse Side

DURANGO, COLO.