. 3.

. y . W . W

: (**1**

LEASE 2 2 9	

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF-078998
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
	San Juan 32-7 Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🔞	San Juan 32-7 Unit
well gas X other	
2. NAME OF OPERATOR	9. WELL NO. 1997 1997 1997 1997 1997 1997 1997 199
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME South Los Pinios
3. ADDRESS OF OPERATOR	Fruitland Pictured Cliffs
P.O. Box 90, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA GLAGO DESCOS
below.) AT SURFACE: 1010' FNL & 1590' FEL	
AT SURFACE: 1010' FNL & 1590' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico
	14. API NO. ###################################
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	30-045-23614
ALFORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6739' GR 3 4 3 4 6 5
TEST WATER SHUT-OFF	기 등 대한
FRACTURE TREAT	
SHOOT OR ACIDIZE	A jana igos i sool o bluos bluos pilos pilos
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING MULTIPLE COMPLETE	change on Form 9–330.) Consider the constant of the constant o
CHANGE ZONES	neitoust Berago III Brashal al neihal bluade Bodden bodden
ABANDON*	Mount rago Ir sour co in soft in mailed ma mailed mailed mailed m
(other) Drlg Operations X	neitousten denago llow denago llow denago lo b natural de al nathat no al habitata de al bitata de al bitata de al bitata de al bitata de al bitata de
17 Process Process of College Process	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di 	rectionally drilled give subsurface locations and
measured and true vertical depths for all markers and zones pertinen	t to this work.)* 등등등을
	1000 H 100 H
March 20, 1980	
Howco cmted w/100 sks Cl 'B' 65/35 poz w/2% g	rel & 12-1/2# fine gilsonite/sk
Tailed w/150 sks Cl 'B" w/6% gel & 10# gilson	nite/sk. Plug displaced w/2 bbls
acetic acid & 21 bbls wtr & down @ 0745 hrs.	Wilson ran Temp survey: 15
cmt top @ 1550' w/PBID @ 3832'. Rig released	1 @ 1100 hrs.
NOW WAITING ON FRAC & COMPLETION.	
· 보기하는	
	135 THE VIII

Subsurface Safety Valve: Manu. and Type _____ 18. I hereby certify that the foregoing is true and correct TITLE Production Clerk DATE 3-27-80

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: DATE

oned oneday