UNITED STATES DEDARTMENT OF THE INTERIOR

	Form Approved. Budget Bureau No. 42–R1424		
٦	5. LEASE		
l	SF 078138		
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
S	7. UNIT AGREEMENT NAME		
UTC/IX	8. FARM OR LEASE NAME		
	Morris A		
	9. WELL NO. 3R		
	10. FIELD OR WILDCAT NAME Azted P.C.		
01	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
e 17	AREA Sec. 28,T-30-N, R-11-W N.M.P.M.		
	12. COUNTY OR PARISH 13. STATE		
	San Juan New Mexico		
rice,	14. API NO.		
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5079 GL	Walker I	
F:	3079 01	fptiff.si	
	A many and a management of the second of the		
.	(NOTE: Report results of multiple completion or zone change on Form 9–330.)		
CICAL	CHANGE		
FON, I	SURVEY N. IVI		
ell is d	e all pertinent details, and give pertinent dates, lirectionally drilled, give subsurface locations and nt to this work.)*		
#, O 1	K. Perfed 2213,2218,2235,2240,		
' W,	/1 SPZ. Fraced w/64,000# 20/40		
538	gal. wtr.		
	Socility /		
	VEL TIATO		
	NL 25 1980	1	

DEPARTMENT OF THE INTERIOR	SF 0/8138
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for such proposals.)	-1
1. oil gas	Morris A 9. WELL NO.
2. NAME OF OPERATOR	3R
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Azted P.C.
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T-30-N, R-11-W
below.) 1510'N, 1550'W	N.M.P.M.
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico
	_ 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
OUDOFOUGHT DEPORT OF	5079' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	and comment of the control of the co
FRACTURE TREAT	The state of the s
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING	change on Form 9-330.)
CHANGE ZONES U. S. GEOLOGICAL	L SURVEY
ABANDON* FARMINGTON,	N. M.
(other)	and the state of t
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine 3-13-80: PBTD 2400'. Tested casing to 4000#, 0 2255,2260,2292,2298,2339,2346,2361' W sand, 69,000 gal. wtr. Flushed w/538	OK. Perfed 2213,2218,2235,2240, W/1 SPZ. Fraced w/64,000# 20/40
	RECEIVED MAR 25 1980 MAR 25 COM
Subsurface Safety Valve: Manu. and Type	Set @ OIL CONT. 3
18. I hereby certify, that the foregoing is true and correct	
SIGNED TITLE Drilling C1	erk DATE March 17, 1980
(This space for Federal or State o	
	DATE
APPROVED BY TITLE	ACCEPTED FOR RECORD
	106
*See Instructions on Reverse	MAR 24 1980
	·

BY M& Ruchera