5-USGS (Farmington) 1-Ladd 1-File

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	5. LEASE NM 0206995
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME Aztec
2. NAME OF OPERATOR	9. WELL NO. 4-35
Ladd Petroleum Corp. 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Harper Hill Fruitland - PC
Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec 35 T30N R14W
AT SURFACE: 1120' FSL - 1600' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5522' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SUBSEQUENT REPORT OF:	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING MULTIPLE COMPLETE	change on Form 9–330.)
CHANGE ZONES	
ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
11-16-79 Moved in and rigged up Morrow @ 10:00 a.m. 11-16-79. Drille OD 23# N-80 8R LT&C csg. TE w/35 sx class "B" neat. POB @ circulated	88' set @ 89.5' GL. Lemented
pipe while cementing. Preflus sx 2% Lodense w/1/4# cello fla w/1/4# cello flake per sx. Ci Bumped plug w/1600 psi. Relea	Had good circulation and reciprocated shed hole w/5 bbls wtr. Cemented w/75 ake per sx followed by 50 sx neat irculated good cement to surface. ased to 750 psi. Shut in. POB 4:30 p.m
Subsurface Safety Valve: Mariu. 2007 79pe	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	DATE12-10-79
Thomas' A. Dugan /	
(This space for Federal or State of	ffice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	