UNITED STA DEPARTMENT OF TH GEOLOGICAL S

UNITED		5. LEASE SF 078511
DEPARTMENT OF GEOLOGICA		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND	REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to dril reservoir. Use Form 9-331-C for such propose	osals.)	D. TAKWOK ELASE WAME
1. oil gas well other		QUINN 9. WELL NO.
2. NAME OF OPERATOR		4-A 300 A 300
SUPRON ENERGY CORPOR	ATION	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR		Basin Dakota, Blanco Mesaverde
P. O. Box 808, Farmil	ngton, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT I	LOCATION CLEARLY. See space 17	Sec. 19, T-31N, R-8W, N.M.P.M.
AT SURFACE: 1600 ft./S	; 945 ft./E line.	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Same as above.	San Juan New Mexico
	Same as above.	14. API NO.
16. CHECK APPROPRIATE BOX TO) INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA		15. ELEVATIONS (SHOW DF, KDB, AND WD)
		6471 GR.
REQUEST FOR APPROVAL TO:	SUESEQUENT REPORT OF:	
TEST WATER SHUT-OFF	₩	8783 E (2.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4
FRACTURE TREAT	H	
SHOOT OR ACIDIZE		(NOTE: Report results of multiple completion or zone
REPAIR WELL PULL OR ALTER CASING	Π.	change on Form 9–330.)
MULTIPLE COMPLETE	Ħ	그 그는 사람이 있는 6일 사람들이 나를
CHANGE ZONES		
ABANDON*	A.	
(other)		하는 사람들은 사람들이 되었다. 이 바로 유럽 유럽 사람들은 다른 사람들이 되었다. 그 사람들은 다른 사람들이 되었다. 그 바로 가는 사람들이 되었다면 보다 되었다면 보니요. 그렇지 되었다면 보다 되었다면 보니 되었다면 보다 되었다면 보니 되었다면 보다 되었다면 보니 되었다면 보다
	MPLETED OPERATIONS (Clearly state inting any proposed work. If well is on the for all markers and zones pertine	ite all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
. Spudded 13-3/4" surfa	ace hole at 6:30 P.M. 7/2	
2. Drilled surface to to	otal depth of 306 ft. R.	K.B. <u>#1.26.5</u> 2 5.51
		. Landed at 306 ft. R.K.B.
Cemented with 250 sac	cks of class "B" with 2%	Calcium Chloride. Plug down at ace.

- 17. DESCRIBE PROPOSED OR COMPLE including estimated date of starting measured and true vertical depths f
- Spudded 13-3/4" surface 1.
- Drilled surface to total 2.
- Ran 7 joints of 10-3/4" 3.
- Cemented with 250 sacks 6:30 A.M. 7/2/80. Cement cir
- Waited on cement for 12 hours. 5.

6. Pressure - tested casing to 800 P.S.I. for 15 minutes. He	ld (_(•	0)))))))	J	C	(-	-	-	-	-	-	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	-				٠		L	1	1	d	C	C	C	(_1	L	L	L	1]	:	3	8	е	e	E	H						•	3 .	S	91	,e	t	u	าเ	ir	m		,	5	1		•	r	fc	•	3.	.S	P	С	800	0		ng	casing	tested	_		3	sure	Pressur	,	6.
--------------------------------------------------------------	------	----	---	---	---	---	---	---	---	---	---	---	---	---	--	--	--	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	--	--	---	--	---	---	---	---	---	---	---	---	----	---	---	---	---	---	---	---	---	---	---	---	---	--	--	--	--	--	---	-----	---	----	----	---	---	----	----	---	--	---	---	---	--	---	---	----	---	----	----	---	---	-----	---	--	----	--------	--------	---	--	---	------	---------	---	----

Subsurface Safety Valve: Manu. and Type __

Set @ 9

18. I hereby certify that the foregoing is true and correct

ATTLE Production Supt. DATE

July 21 1980

This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: DATE

*See Instructions on Reverse Side