11,144,14

UNITED STATES

UNITED STATES	5. LEASE SF 078998
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME San Juan 32-7 Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas	San Juan 32-7 Unit
well well other 2. NAME OF OPERATOR	#71
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesa Verde
P.O. Box 90, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 9 T31N R7W
below.) at surface: 1040' FNL & 1550' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as above	San Juan New Mexico
AT TOTAL DEPTH: Same as above	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-045-24467
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6571' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone
REPAIR WELL	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	ackslashobe com. f
(other) <u>Drilling Operations</u> X	and the National American
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
11/8/80 Ran temp survey and found top of cement at 2250'; PBTD at 3825'. 11/9/80 Well TD'ed at 1630 hrs. Schlumberger ran IES/GR & FDC/SNP/GR logs. 11/10/80 Ran 74 jts (2337') of 4-1/2" 10.5#, K-55, ST&C set at 3653' to 5990'. Dowell cemented with 235 sx Cl "B" with 4% gel and 1/4 cu.ft Gilsonite/sx. Reversed out 5 bbls of cement. Plug displaced with 63 bbls of water and down at 1945 hrs. 11/11/80 Rig released at 0130 hrs. OFF REPORT UNTIL COMPLETION	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED DONNA Brace TITLE Production Clerk DATE November 13, 1980	
ACCEPTED FUR RECURD (This space for Federal or State of	fice use)
APPROVED BY CONDITIONS OF APPROVED BY	DATE
BY BY SAMINGTON DISTRICT NMOCO	
*See Instructions on Reverse	Side

*See Instructions on Reverse Side