

000 Rio Brazos Rd. Azusa, CA 91701
JAN 27 1999

Santa Fe, New Mexico 87504-2088

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: _____ Date Completed: _____

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: Onsite _____ Offsite _____
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: _____

Approval to backfill the Farnsworth Gas Com A-1E separator pit was obtained from the
OCD, Santa Fe office via certified letter return receipt #: Z-235-437-274 dated
May 27, 1998.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: _____ Sample location _____ Center of pit _____

Closure Sampling: _____
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample depth _____ 3 feet below pit bottom

Sample date _____ 3/28/98 Sample time _____ 9:35 am

Sample Results

Benzene(ppm) _____ 4.130 ppm

Total BTEX(ppm) _____ 184.910 ppm

Field headspace(ppm) _____ N/A

TPH _____ 10,270 ppm

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 8/4/98

SIGNATURE *Duane Zimmerman*

PRINTED NAME DUANE ZIMMERMAN
AND TITLE OPERATIONS ENGINEER

Farnsworth Gas Com A1E
SW/NW Section 17, T30N-R13W
San Juan County, New Mexico

