REPORT, OR OTHER DATA

1 - File

Form Approved. Budget Bureau No. 42-R1424

13. STATE

NM

Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM 030555A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME Dare Devil
1. oil gas well XX other	9. WELL NO. #2
 NAME OF OPERATOR Dugan Production Corp. ADDRESS OF OPERATOR P 0 Box 208, Farmington, NM 87401 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 	10. FIELD OR WILDCAT NAME Pictured Cliffs
	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec 10 T30N R13W

2. NAME OF OPERATOR Dugan Production Corp. 3. ADDRESS OF OPERATOR P 0 Box 208, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1840' FSL - 790' FWL AT SURFACE: AT TOP PROD. INTERVAL: 1755' AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,

14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD)

ange on Form 9-139.)

12. COUNTY OR PARISH

San Juan

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON*

(other)

5720' GL SUBSEQUENT REPORT OF: 2-7/8" csg. (NOTE: Report results of multiple completion or zon

U. S. GEOLOGICAL SURVEY FARMINGION, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 52 jts. 2-7/8" OD, 6.5#, J-55 tbg. for csg. T.E. 1615.27' 10-12-80 set at 1603' GL. Had good circulation and reciprocated pipe while cementing. Cemented w/ 50 sx extended slurry followed by 50 sx class "B" neat. Total slurry 172 cu.ft. Circulated trace of cement to surface. Bumped plug w/ 1000 psi - shut in. P.O.B. at 6:00 a.m. 10-11-80.

Set @ . Subsurface Safety Valve: Manu. and Type _ 18. I hereby certify that the foregoing is true and correct Geologist Jim L Jacobs (This space for Federal or State office use) MAR 26 1981 APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON Clarence