Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

DEPARTMENT OF THE INTERIOR	5. LEASE
DEPARTMENT OF THE INTERIOR	SF-080776
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🗓 other	Mansfield A
well well well other	9. WELL NO.
2. NAME OF OPERATOR	<u>le</u>
Tenneco Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
P. O. Box 3249, Englewood, CO 80155	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 1660' FSL 1700' FEL	Sec. 25, T30N R10W
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. AFI NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	5989' gr.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	GEN.
TEST WATER SHUT-OFF	
FRACTURE TREAT	
REPAIR WELL THE RECE	(NOTE: Report lesults of multiple completion or zone change on Form 9–33AUG 3 1 1981
PULL OR ALTER CASING	change on Form 9-33AUG 3 1 198
	OIL CON. COM.
CHANGE ZONES	(3.2 33.11 33.11
(other)	
FARWINGIC	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent.)	irectionally drilled, give subsurface locations and t to this work.)*
8/13/81 - MIRUSU. NDWH. NUBOP. RIHw/tbg and	3 7/8" bit. Tagged cmt @ 6970'.
Drld to PBTD 7128'. PT csg to 3500 psi. Ok.	Circ hoel w/1% KCL water. Spotted
500 gals 7 1/2% HCL across perfs. POOH w/tbg.	e e
8/14/81 - Perf'd Dakota w/l JSPF as follows: 6	927-38', $6946-52'$, $7020-38'$, and $w/2$
JSPF from 7072-76', 7084-88', 7111-16', total	of 41' and 61 holes. Acidized and
balled off w/2000 gals 15% HCL and 92 1.1 ball	slrs. Ball off complete. Acid
away @ 36 BPM and 2600 psi. Round trip junk b	asket recovered 92 balls. Frac'd
w/90000 gals 30# XL gel and 160000# 20/40 sand	. AIR 70 BPM and 2900 psi. ISIP
1400 psi.	1 11 11 2001
8/15/81 - RIH w/tbg, SN, pump out plug. Tagge	d sand bridge 300' to bottom. Clean
out bridge. Tagged sand fill @ 7065'. Clean	out to PBTD w/toam. Killed well.
Landed tbg @ 6954'. Kicked well around w/N2.	KDMUSU.

Subsurface Safety Valve: Manu. and Type _Set @ __ 18. I hereby certify that the foregoing is true and correct SIGNED _ TITLE Production AnalystDATE _ (This space for Federal or State office use) __ TITLE ___ _____ DATE _

*See Instructions on Reverse Side