

District I
P.O. Box 1980, Hobbs, NM
District II
P.O. Drawer DD, Artesia, NM 88211
District III
000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OK
SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

RECEIVED
2075
OIL CON. DIV.
DIST. 3

PIT REMEDIATION AND CLOSURE REPORT

Operator: CROSS TIMBERS OPERATING CO. Telephone: (505) 632-5200
Address: 6001 HIGHWAY 64, FARMINGTON, NM 87401
Facility or: PAN AM FED GC "B" IE
Well Name _____
Location: Unit or Qtr/Qtr Sec G Sec 31 T 30N R 11W County SAN JUAN
Pit Type: Separator ___ Dehydrator ___ Other VENT
Land Type: BLM X, State ___, Fee ___, Other _____

Pit Location: Pit dimensions: length 15, width 15, depth 4
(Attach diagram) Reference: wellhead X, other _____
Footage from reference: 100'
Direction from reference: 60 Degrees ___ East North X
of
X West South _____

Depth To Ground Water: Less than 50 feet (20 points)
(Vertical distance from 50 feet to 99 feet (10 points)
contaminants to seasonal Greater than 100 feet (0 Points) 0
high water elevation of
ground water)

Wellhead Protection Area: Yes (20 points)
(Less than 200 feet from a private No (0 points) 0
domestic water source, or; less than
1000 feet from all other water sources)

Distance To Surface Water: Less than 200 feet (20 points)
(Horizontal distance to perennial 200 feet to 1000 feet (10 points)
lakes, ponds, rivers, streams, creeks, Greater than 1000 feet (0 points) 0
irrigation canals and ditches)

RANKING SCORE (TOTAL POINTS): 0

100-100000-100000

100-100000-100000

100-100000-100000

Date Remediation Started: 11/30/00 Date Completed: 12/4/00

Remediation Method: Excavation Approx. cubic yards 0
(Check all appropriate sections) Landfarmed Insitu Bioremediation

other PIT TESTED PRIOR TO ANY REMEDIATION.
NO REMEDIATION REQUIRED.

Remediation Location: Onsite Offsite
(ie. landfarmed onsite, name and location of offsite facility)

General Description Of Remedial Action: NA
PIT BACKFILLED X RECONTOURED

Ground Water Encountered: No X Yes Depth

Final Pit: Sample location see Attached Documents

Closure Sampling: (if multiple samples, attach sample results and diagram of sample locations and depths)
Sample depth 3'

Sample date 11/30/00 Sample time 1147

Sample Results

Benzene(ppm)

Total BTEX(ppm)

Field headspace(ppm) 0.0

TPH 143

Ground Water Sample: Yes No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE JAN 29, 2001

SIGNATURE

Jeffrey C. Blagg

PRINTED NAME
AND TITLE

JEFFREY C. BLAGG, NMPE 11607
AGENT FOR CTOC

TRAVEL NOTES: CALLOUT: 11/30/00 0930 ONSITE: 11/30/00 1130

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Blagg / Cross Timbers	Project #:	403410
Sample ID:	Vent Pit C @ 3'	Date Reported:	12-01-00
Laboratory Number:	18895	Date Sampled:	11-30-00
Chain of Custody No:	9163	Date Received:	11-30-00
Sample Matrix:	Soil	Date Extracted:	12-01-00
Preservative:	Cool	Date Analyzed:	12-01-00
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5/- C10)	ND	0.2
Diesel Range (C10 - C28)	143	0.1
Total Petroleum Hydrocarbons	143	0.1

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: Pan Am Fed. GC "B" 1E.


Analyst


Review

09163

[illegible]