

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

ADDRESS OF OPERATOR  
P O Box 208, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

below.)  
AT SURFACE: 790' FNL - 1650' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

## CHANGE ZONES

ABANDON\*

(other)

SUBSEQUENT REPORT OF:

XX Spud, surface casing

(NOTE: Report results of multiple completion or zone change on Form G-230)

OIL CON. COM.  
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-8-81

245 W.O.C.

245 W.O.C.  
MI & RU Four Corners Drlg. Rig #9. Spudded 12 1/4" hole at  
3:45 p.m. 12-7-81. Drilled to 245'. 3/4" at 240'. Ran 6  
jts. 8-5/8" OD, 24#, 8 Rd, ST&C csg. T.E. 229' set at 241'.  
RKB. Cemented w/ 135 sx class "B" plus 2% CaCl. P.O.B. at  
12:30 a.m. 12-8-81. (Cement circulated.)

Subsurface Safety Valve: Manu. and Type

Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

"TITLE

DATE \_\_\_\_\_

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE \_\_\_\_\_

APPROVED BY \_\_\_\_\_ ✓  
CONDITIONS OF APPROVAL, IF ANY:

NMOCCH

DEC 1 1981

FARMINGTON DISTRICT

BY