


OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	



5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
9. Well No.	
10. Field and Pool, or Wildcat	
Meadows Gallup <i>Ext</i>	
12. County	
San Juan	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator  
Roy L. Owen dba The Owen Drilling Fund

3. Address of Operator  
c/o Simmons Engineering P.O. Box 48 Farmington, N.M. 87401

4. Location of Well  
UNIT LETTER C 700 FEET FROM THE North LINE AND 1650 FEET FROM  
THE West LINE, SECTION 33 TOWNSHIP 30N RANGE 15W N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)  
5196 RT

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Perforations and Stimulation

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-3-82 Moved completion tools on location. Cleaned out to DV Tool @ 2880'. Tested to 2000 psig. Drilled DV and cleaned out to PBTD @ 4272'. Tested to 3000 psig. Circ. hole w/ 2% KCL water, spot 500 gals. 7½% HCL @ 4200'. Ran Gamma Ray and CCL logs.
- 1-4-82 Perforated 4198-4208 w/ 10 holes. Acidized w/ 500 gals. 15% HCL. Frac'd w/ 48,000# 10/20 sand in 30# gel & 300 SCF/Bbl CO<sub>2</sub>. Set RBP @ 4180'. Tested to 3000 psig. Perforated 4083-4154 w/ 12 holes selectively. Acidized w/ 500 gals. 15% HCL, frac'd w/ 42,000# 10/20 sand in 30# gel and 300 SCF/Bbl CO<sub>2</sub>. Cleaned out to RBP and retrieved. Cleaned out to PBTD. Landed well w/ btm. tbgs. @ 4203'.
- 1-5-82 Swabbed 89 barrels fluid (9 bbls oil) Rigged down completion tools. Presently waiting on production equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.D. Simmons TITLE Agent DATE 1-9-82  
Original Signed by CHARLES GHOLSON  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE FEB 17 1982