

F

30-045-25368

4-12-82

F. Loc. 1520/S;790/W Elev. 5702 GL Spd. Comp. TD PB

Casing S. @ W Sx Int. @ W Sx Pr. @ W Sx T. @
Csg. Perf. Prod. Stim.T
R
A
N
S

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. s

TOPS		NITD X	Well Log	TEST DATA						
Kirtland		C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland		C-104	Electric Log							
Pictured Cliffs			C-122							
Cliff House		Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout		160								
Manco										
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada										

P

Fruitland
Chaco Mesa Co. SJ S 33 T 30N R 12W U L Oper. Amoco Production Co. Lse. McGrath Gas Com C No. 1

McGrath Gas Com C #1

L-33-30N-12W

AMOCO PRODUCTION CO.

4-12-82

F. Loc. 1520/S; 790/W

Elev. 5702 GL

Spd.

Comp

—TD

_PB

Casing S.

-@-

Sx.

Int

—@—

W

Sx

Pr

— (C)

W

—S

1.

6

Csg.Perf.

Prod. Stim.

**T
R
A
N
S**

I.P. _____ BO/D
MCF/D

BO/D

Hr

SICP

PSI After

Days GOR

Grav.

1st Del.

S

TOPS		NITD X	Well Log	TEST DATA						
		C-103	Plot X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland										
Fruitland		C-104	Electric Log							
Pictured Cliffs			C-122							
Cliff House		Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout										
Mancos										
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada										

160

Fulcher Kutz Co. SJ 5 33 T 30N R 12W UL Oper. Amoco Production Co. Les. McGrath Gas Com C No. 1

Drawer 600
Farmington, New Mexico 87499

CERTIFIED

Amoco Production Company
501 Airport Drive
Farmington, New Mexico 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) well No. 1
E L.M. Barton, NW¼SW¼ sec 12, and 1 McGrath Gas Com "C", NW¼SW¼ sec. 33,
both in T. 30 N., R. 12 W., San Juan County, New Mexico, leases
Santa Fe 001239 and New Mexico 021122 Respectively. As discussed with
Robert Murphy of your Company on April 11, 1983, the subject APDs are
rescinded and returned due to drilling not being commenced within one
year of the approval date.

You are required to request surface rehabilitation instructions from
this office if construction activities occurred on the referenced drill
sites. If this office does not receive comment within 15 days, it will
presume that no construction occurred and proceed accordingly. Later
discovery that construction activities have in fact occurred, will
result in assessment of liquidated damages.

Sincerely yours,



for Acting Area Manager

Enclosure

cc: NMOCC

APD

APD