

F

30-045-26031

7-16-84

F. Loc. 1520/N; 815/W Elev. 6416 GL Spd. Comp. TD PB
 Casing S. @ W Cu. ft. Sx. Int. @ W Cu. ft. Sx. Pr. @ W Sx. T. @
 Csg. Perf. Prod. Stim.

T
R
A
N
S

BO/D Grav. 1st Del. Gas
 I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NI/D X	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref.No.
Ojo Alamo		C-103	Plat X							
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres W/320								

P
o
o

Blanco MV Co. SJ S 17 T 31N R 8W U E Oper. Union Texas Pet. corp. Quinn No. 3 A

Quinn #3-A

E-17-31N-8W

UNION TEXAS PETROLEUM CORP.

F

30-045-26031

7-16-84

F. Loc. 1520/N: 815/W Elev. 6416 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

BO/D _____ Grav. _____ 1st Del. Gas _____
 MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NI TD	X	Well Log	TEST DATA						
Cjo Alamo		C-103		Plat X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-104		Electric Log							
Fruitland				C-122							
Pictured Cliffs		Ditr		Dfa							
Chacra		Datr		Dac							
Cliff House		Abandon location									
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		Acres W/320									

P
o
o

Basin Dak. Co. SJ S 17 T 31N R 8W U E Oper. Union Texas Pet. Corp. Lse. Quinn

No. 3 A