

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-045-26328
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Blackwood & Nichols Co., Ltd.
3. Address of Operator P. O. Box 1237, Durango, Colorado 81302

7. Lease Name or Unit Agreement Name Northeast Blanco Unit
8. Well No. 212
9. Pool name or Wildcat Basin Fruitland Coal

4. Well Location Unit Letter <u>O</u> : <u>1030</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>1</u> Township <u>31N</u> Range <u>7W</u> NMPM <u>San Juan</u> County
---

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
6515' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Packer Installation in Pressure Observation Well <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-22-91 MIRU. Shut down over weekend.  
6-25-91 Blow well down. Nipple up BOP. Could not circulate - tubing plugged with coal. Pick up 2 stands tubing. Establish circulation. TOOH with tubing. RIH with packer and 101 jts 2-3/8" tubing. Set packer at 3100' with 8,000# tension. Nipple down BOP, nipple up wellhead. Shut in well.

RECEIVED

JUL 24 1991

OIL CON. DIV  
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Al Rector TITLE Operations Engineer DATE 7/02/91

TYPE OR PRINT NAME Al Rector TELEPHONE NO. 303/247-0728

(This space for State Use)

Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUL 24 1991

CONDITIONS OF APPROVAL, IF ANY: