

F

30-045-26644

12-26-85

F. Loc. 970/S; 1720/E Elev. 5869 GL Spd. Cu. ft. Comp. TD Cu. ft. PB
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ T Gas
 Csg. Perf. Prod. Stim.

Grav. 1st Del. Gas
 I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS	NITD X	Well Log	TEST DATA							Ref. No.
Ojo Alamo	C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104	Electric Log								
Fruitland		C-122								
Pictured Cliffs	Ditr	Dfa								
Chacra	Datr	Dac								
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
	Acres 155.30									

P
 o
 o
 FullcherKutzPC Co. SJ S 31 T30N R11W UO Oper. Amoco Production Co. Lse. WilliamsFed. GasCom A No. 1

Williams Fed. Gas Com A #1

O-31-30N-11W

AMOCO PRODUCTION CO.

F

30-045-26644

12-26-85

F. Loc. 970/S; 1720/E Elev. 5869 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @ T Gas
 Csg. Perf. Prod. Stim.

Grav. _____ 1st Del. Gas
 I.P. BO/D MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil

TOPS		NI TD	X	Well Log	TEST DATA							Ref. No.
Ojo Alamo		C-103		Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104		Electric Log								
Fruitland				C-122								
Pictured Cliffs		Ditr		Dfa								
Chacra		Datr		Dac								
Cliff House												
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												
				Acres 155.30								

P
 o
 o
 Crouch Mesa MV Co. SJ S 31 T 30N R 11W U O Oper. Amoco Production Co. Lse. Williams Fed. Gas Com A No. 1

MM-048574 (WC)
3162.3-1(F) (019)

MAY 02 1988

CERTIFIED--RETURN RECEIPT REQUESTED
F-735-030-079

Amoco Production Company
2325 E. 30th Street
Farmington, NM 87401

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 1 Williams Federal Gas Com A, SW/4SE/4 sec. 31, T. 30 N., R. 11 W., San Juan County, New Mexico, lease MM-048574. The subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this Office if construction activities occurred on the referenced drill site. If this Office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment of liquidated damages.

Sincerely,

/s/ Arlan G. Hiner

FOR: Ron Fellows
Area Manager

1 Enclosure

cc:
BROCD

ABANDONED LOCATION

RECEIVED
MAY 16 1988
OIL CON. DIV.
DIST. 3