

Caller Service 4104
Farmington, New Mexico 87499

CERTIFIED—RETURN RECEIPT REQUESTED
P-488-632-865

El Paso Natural Gas Company
P.O. Box 4289
Farmington, NM 87499

AUG 20 1987

RECEIVED
AUG 21 1987
OIL CON. DIV.
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

1. No. 14 Schumacher, SW/4NE/4 sec. 17, T. 30 N., R. 10 W., San Juan County, New Mexico, lease SF-077764.
2. No. 2 De Ma Haz Za, NW/4NW/4 sec. 18, T. 26 N., R. 8 W., San Juan County, New Mexico, lease 14-20-603-772.
3. No. 38A San Juan 30-6 Unit, SW/4NW/4 sec. 27, T. 30 N., R. 7 W., Rio Arriba County, New Mexico, lease SF-079074.
4. No. 76A San Juan 30-6 Unit, SE/4SE/4 sec. 24, T. 30 N., R. 7 W., Rio Arriba County, New Mexico, lease SF-079392.
5. No. 64A San Juan 30-6 Unit, SW/4SE/4 sec. 11, T. 30 N., R. 7 W., Rio Arriba County, New Mexico, lease NM-012710.

As discussed with Peggy Doak of your company on August 13, 1987, the subject APDs are rescinded and returned due to drilling not being commenced within a six month extension period following the original one year approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment for noncompliance.

Sincerely,

/s/ John L. Keller

Ron Fellows
Area Manager

ABANDONED LOCATION

5 Enclosures

cc: BIA, Window Rock NMOCD ADO (015) Well files (5)
3162.3-1(I/F) Suspense FSM 30th Street 016:SMason:csH:08/19/87

F

30-045-26705

2-3-86

F. loc. 1450/N: 1450/E Elev. 6418 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

BO/D _____ Grav. _____ 1st Del. Gas _____
 MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NITD X	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref. No.
Ojo Alamo		C-103	Plat X							
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfo							
Chacra		Datr	Dac							
Cliff House		VEDNG								
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

E/311.82

Acres

P
o

Basin Dak. Co. SJ S 17 T 30N R 10W U G Oper. Meridian Oil Inc. Lse. Schumacher No. 14

Schumacher #14

G-17-30N-10W

Meridian Oil Inc.