

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

| | | |
|--|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> | | 5. LEASE DESIGNATION AND SERIAL NO. SF-078505 |
| 2. NAME OF OPERATOR Union Texas Petroleum | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A |
| 3. ADDRESS OF OPERATOR 375 U.S. Highway 64, Farmington, New Mexico 87401 | | 7. UNIT AGREEMENT NAME N/A |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1660' FSL & 1794' FWL | | 8. FARM OR LEASE NAME SEYMOUR |
| 14. PERMIT NO. | | 9. WELL NO. 10 |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6401' G.L. | | 10. FIELD AND POOL, OR WILDCAT Sedro Canyon Fruitland |
| | | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 23-T31N-R9W |
| | | 12. COUNTY OR PARISH San Juan |
| | | 13. STATE NM |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|--|---|---|--|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> | WATER SHUT-OFF <input type="checkbox"/> | REPAIRING WELL <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | MULTIPLE COMPLETE <input type="checkbox"/> | FRACTURE TREATMENT <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | ABANDON* <input type="checkbox"/> | SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | (Other) Spud and Surface Casing <input checked="" type="checkbox"/> | |
| (Other) <input type="checkbox"/> | | (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Union Texas Petroleum wishes to advise that this well was spud at 6:30 PM on 8/27/87. A 12-1/4" hole was drilled to 620' KB. Run 9-5/8", 36#, K-55 casing to 617' KB, cementing to surface with 400 sx (472 cu.ft.) CI "B" with 2% CaCl2 and 1/4# flocele/sk. Circulate 20 bbls (112 cu.ft.) of cement to surface. Nipple up BOP and manifold, testing to 1000 psi. Held OK. Test casing to 600 psi. Held OK. Drill 8-3/4" hole out of surface.

RECEIVED
SEP 09 1987
OIL CON. DIV. J
DIST. 3

18. I hereby certify that the foregoing is true and correct

| | | |
|--|---------------------------------|-------------------------|
| SIGNED <u>Robert C. Frank</u> | TITLE <u>Permit Coordinator</u> | DATE <u>08/30/1987</u> |
| (This space for Federal or State office use) | | |
| APPROVED BY _____ | TITLE _____ | DATE <u>SEP 03 1987</u> |
| CONDITIONS OF APPROVAL, IF ANY: | | |

FARMINGTON RESOURCE AREA
BY Smm

*See Instructions on Reverse Side

NW000