Form 3160-5 November 1983) Formerly 9-331)  DEPARTMENT OF THE INTERIOR  BUREAU OF LAND MANAGEMENT  SUBMIT IN TRIPLICATE* (Other Instructions on reverse side)  BUREAU OF LAND MANAGEMENT	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985  5. Lease designation and serial no. SF-078511  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS. V.D.  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.)  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.)  (Do not use this form for proposals.)	N/A T. UNIT AGREEMENT NAME
OIL GAB OTHER OTHER	N/A 8. FARM OR LEASE NAME
Union Texas Petroleum  3. ADDRESS OF OPERATOR Highway 64 Farmington NM 87401	Quinn 9. WBLL HO.
3/5 US Highway 64, Farming con, Am 6/401	10. FIBLD AND POOL, OR WILDCAT
See also space 17 below.) At surface  1450 FSL; 900 FEL	Wildcat Fruitland  11. SBC, T., B., M., OR BLE. AND SURVEY OR AREA  Section 19-T31N-R8W  12. COUNTY OR PARISE 18. STATE
6468 G.L.	San Juan NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data
TEST WATER SHUT-OFF  PRACTURE TREAT  SHOOT OR ACIDIZB  REPAIR WELL  (Other)  17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent details, and give pertinent to this work.)  Union Texas Petroleum wishes to advise that thi	
5:00 P.M. 10/7/87. A 12-1/4" hole was drilled 9-5/8", 36#, K-55 casing to 381' KB, cementing 205 sx (242 cu.ft.) Cl "B" with 2% CaCl2 and 1/Circulate 8 bbls (45 cu.ft.) of cement to surfa and manifold, testing to 1000 psi. Held OK. T 600 psi. Held OK. Drill 8-3/4" hole out of su	to 386' KB. Run to surface with 4# flocele/sk. ce. Nipple up BOP est casing to
O/L C	7231987 DIV.
18. A bereby certify that the foregoing is true and correct SIGNED TITLE  (This space for Federal or State office use)	DATE 10/14/87
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE

\*See Instructions on Reverse Side