

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well GAS	RECEIVED DEC 03 1989 OIL CON. DIV DIST. 3	5. Lease Number NM-0607
2. Operator Meridian Oil Inc.		6. If Indian, All.or Tribe Name
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499		7. Unit Agreement Name
4. Location of Well 800'N, 1010'E		8. Farm or Lease Name Sunray H Com
		9. Well No. 200
		10. Field, Pool, Wildcat Basin Fruitland Coal
		11. Sec. T. R. M. or Blk Sec. 11, T-30-N, R-10-W NMPM
14. Permit No.	15. Elevations 6540 'GR	12. County San Juan
		13. State NM

16. Intent to/Subsequent Report of :

17. Describe proposed or completed operations:

At the conclusion of completion operations (perforating and fracture stimulating), it is intended to perform remedial cementing operations as follows:

1. Set 5 1/2" drillable bridge plug @ 2900'. Test to 3000#.
2. Perforate 2 - 0.5" squeeze holes at a depth above cmt. top as determined from cement bond log.
3. Set 5 1/2" cement retainer 50' above squeeze holes.
4. Establish circulation through bradenhead and cement with 510 sx (985 cu.ft.) 65/35 Class "B" Poz w/6% gel, 2% calcium chloride and 1/2 cu.ft./sx perlite. Circulate cmt. to surface.
5. Drill out cmt retainer and cmt. Test squeeze holes to 1500 psi.
6. Drill out bridge plug.
7. Land tbg, rig down and release rig.

18. Authorized by:

Charles W. Munn

10/25/89
Date

NOTE: This format is issued in lieu of US BLM Form 3160-5

(This space for Federal or State office use)

APPROVED BY

TITLE

DEC 03 1989

CONDITION OF APPROVAL, IF ANY:

NMOOD

APPROVED

AREA MANAGER