



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA  
1235 LAPLATA HIGHWAY  
FARMINGTON, NEW MEXICO 87401



NM-10561 et. al. (WC)  
3162.3-1.0 (019)  
IN REPLY REFER TO:

CERTIFIED - RETURN RECEIPT REQUESTED  
P 253 046 160

DEC. 1 1 1990

Dugan Production Corporation  
P.O. Box 420  
Farmington, NM 87499

## ABANDONED LOCATION

Gentlemen:

Enclosed are your Applications for Permit to Drill (APD's) for the following wells:

1. No. 2 Atlantis, NW/4NE/4 sec. 3, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-10561.
2. No. 3 Atlantis, SW/4NW/4 sec. 3, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-10561.
3. No. 1 Pompay, NE/4NW/4 sec. 4, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-12086.
4. No. 2 Pompay, NE/4NW/4 sec. 4, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-12086.

As discussed with Jim Jacobs of your company on October 18, 1990, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date and within the second six month extension period.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office has not received comment within 30 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

Ron Fellows,  
FOR Area Manager

cc: New Mexico Oil Conservation Division, 1000 Rio Brazos Road,  
Aztec, NM 87410

**RECEIVED**  
DEC 12 1990  
OIL CON. DIV  
DIST. 3


30-045-27093

9/26/88

F

F. loc. 1660N;1040W Elev. 5743 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PB \_\_\_\_\_  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Prod. Stim. \_\_\_\_\_ T Gas

Grav. \_\_\_\_\_ 1st Del. Gas \_\_\_\_\_  
 I.P. \_\_\_\_\_ BO/D \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil \_\_\_\_\_

TOPS		NI TD X	Well Log	TEST DATA							Ref.No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Frctured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
			Acres 160								

P  
o  
i

WC PC Co. SJ S 3 T 30N R 14W U E Oper. DUGAN PRODUCTION CORP. • Loe. ATLANTIS

No. 3

ATLANTIS#3

E-03-30N-14W

DUGAN PRODUCTION CORP.