

12. ✓ No. 291 Nye, 1470' FSL & 1570' FWL, sec. 8, T. 29 N., R. 10 W., San Juan County, New Mexico, lease SF-078197.

13. ✓ No. 100 Newberry, 1390' FSL & 1850' FWL, sec. 17, T. 31 N., R. 12 W., San Juan County, New Mexico, lease NM-021124.

14. ✓ No. 291 Neudecker Com, 1850' FSL & 1450' FWL, sec. 13, T. 29 N., R. 10 W., San Juan County, New Mexico, lease SF-080655.

15. ✓ No. 507 Murphy E Com, 1190' FNL & 920' FEL, sec. 34, T. 30 N., R. 11 W., San Juan County, New Mexico, lease SF-043260-B.

The subject APDs are rescinded and returned pursuant to your written instructions dated November 29, 1989.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment of liquidated damages.

Sincerely,

Ken Townsend

John L. Keller
FCR Chief, Branch of Minerals

15 Enclosures

cc:
NMOCD, Aztec