Ferm 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on re-

SUBMIT IN TRIPLICATE.

roim appioved. Budget Burcau No. 1004-0135 Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO

SE079082

BUREAU OF LAND MANAGEMENT

SUNDRY	NOTICES	AND	REPORTS	ON	WELLSVE
---------------	---------	-----	----------------	----	---------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir,

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME 88 00T 27 Mil0: 26 WELL XX WELL Northeast Blanco Unit OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR Blackwood & Nichols Co. Northeast Blanco Unit 9. WELL NO. 3. ADDRESS OF OPERATOR P. O. Box 1237, Durango, CO 81302 445 LOCATION OF WELL (Report location clearly and in accordance with any State re-See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT Basin Fruitland Coal At surface 1. SEC., T., B., M., OR BLK. AND BURYET OR ARMA 957' FSL, 827' FWL DEC 07 1989 Sec. 25, T31N, R8W, NMP 15. ELEVATIONS (Show whether DF, RT, CHOCK) CON. DIV 12. COUNTY OR PARISH 13. STATE 14. PERMIT NO. 30-045 27246 San Juan New Mexico DIST. 3 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF : TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL ALTERING CASING FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT SHOOTING OR ACIDIZING ABANDON MENT* ABANDON* SHOOT OR ACIDIZE Cementing REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Drilled to Spud 12-1/4" hole at 9:30 p.m., 9-16-89. 9-17-89 320'. Ran 7 jts (309.73') 9-5/8" 36 #/ft K-55, LT&C Lone Star 9-18-89 steel casing. Notched collar at 319'.

(288 cf) of Class B cement with 2% CaCl, + 1/4 #/sk Displaced with 22.75 Bbls of water. cellophane flake. Plug down at 7:00 p.m., Maximum pressure 200 psig.

9-17-89. Circulated 20 Bbls of cement. Pressure tested BOP to 600 psig - held OK.

Drilled to TD at 3009". 9-20-89

9-19-89

Ran 69 jts of North Star 7", K-55 23 #/ft ST&C casing and 9-21-89 1 jt (29.56') of US Steel 7" N-80, 23 #/ft LT&C casing, shoe at 3008', insert float at 2963'. Pumped 20 Bbls of mud flush ahead of 480 sx (811 cf) of 65/35 POZ + 6% gel + .6% Halad 322 FLA + 1/4 #/sk Flocele, LCM. Tailed in with 100 sx (115 cf) of Class B neat + 1/4 #/sk Flocele. Displaced with 115 Bbls of fresh water. Maximum pressure Did not bump plug, float held. Circulated 21 Bbls of good cement. Plug down at 10:35 a.m., 9-20-89.

18. I hereby certify that the foregoing is true and our	1945 A	
SIGNED William Fellows	FITLE Operations Manager	ATE 10-25 89
William F. Clark		ACCEPTED FOR RICORD
(This space for Federal or State office use)		
APPROVED BY	TITLE	DEC DE 1989
CONDITIONS OF APPROVAL, IF ANI.		FARMINE NOW RESOURCE AREA
	78.05g	KIL
	*C 1 () D C:J.	