
DEVIATION REPORT

COMPANY_	Northw	ADDRESS_	3539	E. 30th -		Farmington,		NM	8740			
LEASE	San Juan	32-8 Unit	WELL_	207	UNIT LETTER	N		SEC_22	T 31N	R	8W:	. B
POOL and	FORMATIO	NBasin	Basin Fruitland Coal				_ c	COUNTY	San Juan	 	·	
			•	- 2								

1/4° - 241' 1/2° - 738' 3/4° - 1382' 3/4° - 2078' 1° - 2145' 3/4° - 3050'



							ì	I Mar.	9		
				·	··· · ································			·	••		
Cert	tificate:	I, th	e undersi	gned, sta	te that I	, Carr	ie Harm	on t Pipeline	Cornor	atio	
am a my s	authorize supervisi	d by sa on and	id Compan direction	y to make	this rep	ort which	h was p	repared by n are true	me or	unde	
	my knowle	ŭ),	Lai	10 4	Janne	1		
-Subs	icribed ai	nd swori MALEEAL TINE CO	to befor	re me this	<u></u> da∵	y of <i>/</i>	Mar c		, 19 <u>-</u>	<u>C</u>	
HOTA	interi		+ 162	JUAN COU	ITY, NEW I	MEXICO			•		
and the same of th	.y com	пивыел Ех	Pires:	My	/ Commiss	ion Expir	es	49.4.	ζ		