Form 3160-5 \*(December 1989)

Budget Bureau No 1004-0135 Expires: September 30, 1990 Lease Designation & Serial #

FORM APPROVED

SF078970	

<b>Y</b>		A	ON WELLS	H Cook
SUNDRY	NOTICES AND	KRLOKIS	UM WELLIAM MU	:L NUG.
	to to drill de	epen or reenti	ry to a different	leach vot.
Do not use this tolk for pr	APPLICATION FOR PERM	IIT-" for such	proposals	- AM 11:47

If Indian, Allottee/Tribe Name

7. If Unit or CA, Agmt. Design.:

	SUBMIT	IN TRIPLIC	other ARRAMA		. ·	r Ant
1. Type of Well:	oil well	gas well X	other		+ 1	C/NOU
2. Name of Operator:	Blackwood	& Nichols Co., Lt	d.			
3. Address of Operator:	P.O. Box '	1237, Durango, CO	81302-1237			
4 location of Well: (Fo		., R., M., or Surv	ey Pacting (98)	GRW	E	(A)

Northeast Blanco Unit 8. Well Name and No.: N.E.B.U.# 438

9. API Well No.:

30-045-27659 10. Field & Pool/Expltry Area:

Basin Fruitland Coal 11. County or Parish, State: ...

San Juan, New Mexico

1210' FNL, 1245' FEL Section 18, I31N, ROW.

OIL CON DIV.

		OIL CON. DIV.			
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE DISTLICE, REPORT, OR OTHER DATA				
	TYPE OF SUBMISSION		Change of Plans		
	Notice of Intent _XX_ Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other:	XX_ New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection f multiple completion on Well Completion		
		(Note: Report results of or Recompletion Report	and Log form.)		

- 13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
- Spud 12-1/4" surface hole at 8:15 p.m., 5-14-90. Drill to 320'. Run 7 jts (299.69') 9-5/8" 36# K-55 casing, set at 312'. Cement with 250 5-15-90 sx (295 cf) Class B with 2% CaCl2 and 1/4 #/sk cellophane flake. Displace with 21.3 Bbls water. Circulate 21 Bbls cement to surface. Good circulation throughout. Plug down at 4:15 a.m., 5-15-90.

Pressure test 9-5/8" casing and BOPs to 600 psi for 30 minutes - held 5-16-90 OK.

5-18-90

Run 71 jts (3038.29') 7" 23# K-55 casing, set at 3050'; insert float at 3006'. Cement with 440 sx (726 cf) Class B 65/35 with 6% gel, .6% 5-19-90 Halid 322, and 1/4 #sk flocele. Tail with 125 sx (147.5 cf) Class B 1/4 #/sk flocele. Displace with 119.5 Bbls water. throughout. Did not circulate cement to surface, temperature survey showed cement top at 500'. Bump plug at 8:35 a.m., 5-18-90.

sho	wed cement	top at 500'.	Bump pru	g at 8.33 a	· · · · · ·	
14. I hereby certif	y that the forego	ing is true and correct	 [AMS Title	: ADMINISTRATIVE N	TED FOR RECORD	
		al or State office use)			UN 27 1990	
Appr Cons	oved By itions of approva	l, if amy:	Title		NGTON RESOURCE AREA	
				BY -,22	A service of agen	vv or

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency or the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.