## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wel	lls
1. Type of Well GAS	5. Lease Number SF-080376 6. If Indian, All. or Tribe Name
2. Name of Operator	7. Unit Agreement Name
Meridian Oil Inc.  3. Address & Phone No. of Operator	San Juan 32-9 Unit 8. Well Name & Number San Juan 32-9 U #107
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 1763'GSL, 1134'FWL Sec.9, T-31-N, R-9-W, NMPM	10. Field and Pool Pictured Cliffs 11. County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	, REPORT, OTHER DATA
_x_ Notice of Intent Abandonment	tion _ Change of Plans _ New Construction
Subsequent Report Plugging Back	Non-Routine Fracturing Water Shut off
	_ Water Shut Off _ Conversion to Injection
It is intended to repair this well in the following MOL&RU. Run a cement bond log to locate he squeeze holes and circulate to surface.	TUP
SEP COLCU	
14. I hereby certify that the foregoing is true and co	orrect.
Signed Segay had sick (GL) Title Regulatory Af	
(This space for Federal or State Office use) APPROVED BYTitle CONDITION OF APPROVAL, if any:	APPROVED
	SEP 02 1992

NMOCD