

RICHMOND PETROLEUM INC.

Federal 30-9-27 #2
Sec. 27, T30N, R9W
San Juan County, New Mexico

SLOPE TESTS

Depth

250'
500'
1000'
2500'
2700'

Hole Deviation

1/2 Degree
1/2 Degree
3/4 Degree
1 Degree
1 Degree

RECEIVED

JAN 24 1991

State of New Mexico)
County of San Juan) ss

PL CON. DIV.
DEPT. 3

I, DANA DELVENTHAL, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Dana Delventhal

Subscribed and sworn before me this 16th day of January, 1991.

Patricia A. Sills
Notary Public

My Commission Expires August 21, 1994.